

Polycom® RealPresence Debut™

Contents

- [Introducing Polycom® RealPresence Debut™](#)
- [New Features in 1.1.1](#)
- [Release History](#)
- [Security Updates](#)
- [Products Tested with this Release](#)
- [Corrected Issues](#)
- [Known Issues](#)

Introducing Polycom® RealPresence Debut™

The Polycom RealPresence Debut™ system is an all-in-one micro-codec video endpoint. The system is designed for use in enterprise environments that require a high-quality video and collaboration tool that is easy to deploy and use in huddle rooms and small conference areas.



New Features in 1.1.1

There are no new features in this release for version 1.1.1.

Release History

This following table lists the release history of RealPresence Debut.

Release History

Release	Release Date	Features
1.1.1	July 2016	Includes escalation fixes and documentation updates.
1.1.0	May 2016	Includes support for new user interface languages, RealPresence Resource Manager updates, and provisioning updates; adds support for the Polycom RealPresence Cloud Global Directory, camera settings, background settings, and daylight savings time.
1.0.1	January 2016	Includes escalation fixes and documentation updates.
1.0.0	December 2015	First release of RealPresence Debut hardware and software.

Security Updates

This release includes the following security-related changes:

- CVE-2014-3566, Disables SSLv3 to fix the POODLE vulnerability.
- CVE-2015-2808, Removes RC4 ciphers to fix the Bar Mitzvah vulnerability.

Please refer to the [Polycom Security Center](#) for information about known and resolved security vulnerabilities.

Software Key Codes

You need a key code to update the system software. A *key code* is the number that activates software on a specific system. A key code is valid only on the system for which it is generated.

Make a note of your system serial number. You must provide this number in order to get the key codes that activate software updates. The 14-digit *serial number* is the unique number that identifies your system. You can find it on the System Information screen and on a label on the system. Serial numbers are case sensitive.

Obtain Software Key Codes and Update Software

You can obtain software key codes for a single RealPresence Debut system and update the system software.

To Obtain Software Key Codes and Update Software:

- 1 On a computer, open a browser and navigate to support.polycom.com.
- 2 Under Licensing & Product Registration, click **Activation/Upgrade**.
- 3 Log in to your account.
- 4 Click **Site & Single Activation/Upgrade**.
- 5 Follow the onscreen instructions to request the key code. Make a note of this number for use during installation.
- 6 Copy the RealPresence Debut upgrade package to your computer system.
- 7 Enter the IP address of the RealPresence Debut system and log into the web interface using the Chrome web browser. The default user name is **admin**.
- 8 Go to **Admin Settings > Software Upgrade**.
- 9 Click **Choose File** to select the software upgrade file.
- 10 In the **Software Upgrade Key** field, enter the software key code.
- 11 Click **Upgrade** to start the upgrade process. The RealPresence Debut system will restart automatically and start to upgrade.
- 12 Wait a few minutes, and then refresh your browser.

For information on requesting key codes for multiple RealPresence Debut systems, refer to the Polycom RealPresence Debut Administrator Guide.

Products Tested with this Release

Polycom RealPresence Debut systems are tested extensively with a wide range of products. The following list is not a complete inventory of compatible equipment. It simply indicates the products that have been tested for compatibility with this release.

Polycom strives to support any system that is standards-compliant and investigates reports of Polycom systems that are not interoperable with other vendor systems.



Update your system

Polycom recommends that you upgrade all of your Polycom systems with the latest software versions. Any compatibility issues may already have been addressed by software updates. Go to PolycomService/support/us/support/service_policies.html to see the Current Polycom Interoperability Matrix.

Tested Polycom Products

Type	Product	Version
FW-NAT Traversal	Polycom® RealPresence® Access Director™	4.2.3
	Polycom® Video Border Proxy™ 5300-ST	11.2.24
RealPresence Platform	Polycom® Distributed Media Application™	6.3.2
	Polycom® RealPresence® Resource Manager	9.0.1
	Polycom® RealPresence® Collaboration Server 4000/2000/1800	8.6.3
	Polycom® RealPresence® Collaboration Server 4000/2000 with MPMx	8.5.4
	Polycom® RealPresence® Collaboration Server, Virtual Edition	8.6.3
	Polycom® ContentConnect™	1.5.1
	Polycom® Media Suite®	2.6
	Polycom® RealPresence® Web Suite	2.0
Third-Party Platforms	BroadWorks®	R21 SP1
	BroadSoft® Device Management System	R21 SP1
	Zero Touch Provisioning	Sigma Systems DPM Release 4.3.1
	Cisco TelePresence® Video Communication Server (VCS)	
	Cisco 8710 MCU, 5310 MCU, Codian 4505 MCU	
	BlueJeans	
	Zoom	
Endpoints	Polycom® RealPresence® Group Series	5.1.1
	Polycom® HDX®	3.1.10
	Polycom® RealPresence Debut	1.1.1
	Polycom® RealPresence® Desktop	3.5.1
	Polycom® RealPresence® Mobile	3.5.1
	Polycom VVX® 1500 and Polycom VVX® 600	5.4.1
	Polycom® RealPresence Trio™ 8800	5.4.2
Third Party Endpoints	Cisco C20, SX10, SX20, SX80, MXP G2, MXP 1700	

Resolved Issues

The following table lists the resolved issues for the version 1.1.1 release of RealPresence Debut.

Resolved Issues

Category	Issue Number	Resolved in Release	Description
Calling	ELEP-1258	1.1.0	A RealPresence Debut system was unable to return a call from the call history. This issue has been resolved.
Calling	ELEP-1631	1.1.0	In a call between a RealPresence Debut system and a RealPresence Group Series system, when the RealPresence Debut system hung up from the call, the RealPresence Group Series system did not hang up automatically. This issue has been resolved.
Calling	ELEP-2030	1.1.0	When a RealPresence Debut system called an HDX system using H.323 protocol, the HDX system was unable to hang up from the call. This issue has been resolved.
Camera	ELEP-1560	1.1.0	When a RealPresence Debut system was in a call with a SX20 Quick Set, the RealPresence Debut system was unable to control the far end camera. This issue has been resolved.
Content	ELEP-1540	1.1.0	RealPresence Debut systems were sometimes unable to display content when in a BlueJeans SIP encrypted meeting. This issue has been resolved.
Content	ELEP-1562	1.1.0	When a RealPresence Debut system and a Cisco TelePresence® SX20 Quick Set were in a call and the SX20 Quick Set shared content, sometimes the RealPresence Debut system received delayed content. This issue has been resolved.
Content	ELEP-1644	1.1.0	A RealPresence Debut system was unable to receive content from Zoom in an H.323 call. This issue has been resolved.
Content	ELEP-1662	1.1.0	Polycom HDX® systems were sometimes unable to receive content from RealPresence Desktop clients paired with RealPresence Debut systems. This issue has been resolved.
Content	ELEP-1664	1.1.0	In a call between paired RealPresence Debut and RealPresence Trio™ systems, when both systems shared content, the RealPresence Debut system sometimes received out-of-sync video and audio. This issue has been resolved.
Date and Time	ELEP-456	1.1.0	The RealPresence Debut system was unable to automatically adjust the date and time when daylight savings started and stopped in some time zones. This issue has been resolved.

Resolved Issues

Category	Issue Number	Resolved in Release	Description
Directory	ELEP-1002	1.1.0	Any settings that included passwords were unable be exported or imported to or from the Polycom RealPresence Debut, including settings configured by a provisioning server, calendar server information, and SIP and H.323 server information. This issue has been resolved.
Display	ELEP-1060	1.1.0	The Polycom RealPresence Debut system was unable to wake from sleep mode when connected to some monitors. This issue has been resolved.
Power	ELEP-1216	1.1.0	The Polycom RealPresence Debut system was unable to power on when it was not connected to an external monitor. This issue has been resolved.
Power	ELEP-777	1.1.0	When using Power over Ethernet, it sometimes took up to 3 minutes to power on the RealPresence Debut system. This issue has been resolved.
SIP	ELEP-1575	1.1.0	When a RealPresence Debut system attempted to SIP register through Broadsoft and through session border controller Acme Packet 3820, the registration was sometimes unsuccessful. This issue has been resolved.
Software Update	ELEP-1123	1.1.0	When Polycom RealPresence Debut software was updated some settings on the web interface occasionally did not update correctly. This issue has been resolved.
System	ELEP-2174	1.1.1	Occasionally, RealPresence Debut systems repeatedly restarted after the system powered on or when the system placed a call. This issue has been resolved.
Time Zone	ELEP-1652	1.1.0	RealPresence Debut systems were sometimes unable to save time zone settings after upgrading software. This issue has been resolved.

Known Issues

The following table lists the known issues for the version 1.1.0 release of RealPresence Debut. If a workaround is available, it is noted in the table.

Known Issues

Category	Issue ID	Release	Description	Workaround
Audio	ELEP-534	1.1.0	When two Polycom RealPresence Debut systems are in a call and both meeting participants speak at the same time, occasionally there is an audio echo and occasionally some audio is dropped.	
Audio	ELEP-702	1.1.0	When SmartPairing Auto Detection is enabled on a Polycom RealPresence Debut system and when the monitor volume is high, if the monitor is a low-quality monitor, occasionally there is feedback from the monitor speakers.	
Audio	ELEP-2062	1.1.0	When a RealPresence Debut system is near a TV speaker and when the speaker volume is higher than 80%, sometimes the system microphone picks background noise or echoes.	
Camera	ELEP-2087	1.1.0	In a Fire Wall Network Address Translation (FWNAT) environment, RealPresence Debut systems are sometimes unable to send and receive Far End Camera Control.	
Content	ELEP-1206	1.1.0	During a call, the Polycom RealPresence Debut system might occasionally flash or blur content on a 1080i/60 or 720p/60 monitor.	Use a monitor that supports 1080p30.
Content	ELEP-1271	1.1.0	Sometimes when a RealPresence Debut system joins a video conference by directly dialing a system IP address and conference ID, the system is unable to share content.	
Content	ELEP-1221	1.1.0	When a Polycom RealPresence Debut system uses SmartPairing to pair to a Polycom RealPresence Desktop or Polycom RealPresence Mobile application and when the network connection is low, it can 10-15 seconds for the RealPresence Debut system to send content.	Use the HDMI connection to send content.
Content	ELEP-2064	1.1.0	In a point to point call between two RealPresence Debut systems, occasionally one or both systems are unable to share content when the call rate is 1920 or higher.	
Display	ELEP-72	1.1.0	Some PCs cannot use duplicate monitor mode to send HDMI content.	Select extension monitor mode to send HDMI content.

Known Issues

Category	Issue ID	Release	Description	Workaround
Interoperability Broadsoft	ELEP-280	1.1.0	Incoming and outgoing Polycom RealPresence Debut calls cannot be placed on hold or transferred with BroadWorks call manager.	
Network	ELEP-1606	1.1.0	On a RealPresence Debut system, sometimes after changing the VLAN setting to LLDP or static VLAN settings, the registration times out.	
Network	ELEP-2007	1.1.0	On a RealPresence Debut system, sometimes the control priority in the Static VLAN setting is unable to work for H.323 protocol.	
Network	ELEP-2082	1.1.0	Sometimes the control priority for SIP protocol does not work when RealPresence Debut systems switch from LLDP to Static VLAN settings.	
Power	ELEP-1535	1.1.0	Sometimes RealPresence Debut systems take a long time to power on or are unable to power on using Power over Ethernet.	<ol style="list-style-type: none"> 1 Use a different Power over Ethernet switch. Some power over Ethernet switches may not be compatible with RealPresence Debut systems. 2 Disconnect and reconnect the HDMI cable to the RealPresence Debut system. 3 Use the power adapter to power on the RealPresence Debut system.
Software Update	ELEP-1215	1.1.0	When Polycom RealPresence Debut software update files are downloaded using Apple® Safari® 9, the files are automatically extracted and the RealPresence Debut system is unable to use the files to update the software.	Use a different web browser to download RealPresence Debut software update files or disable the automatic file extraction function in the Safari preferences.
Software Update	ELEP-2100	1.1.0	When a RealPresence Debut system is downgraded to an older software version, all RealPresence Debut system settings are automatically set to default settings.	

Known Issues

Category	Issue ID	Release	Description	Workaround
System	ELEP-502	1.1.0	When two Polycom RealPresence Debut systems are in a call and one system sends 1080p30 video and audio content, occasionally the video content displays with thin flickering lines.	
System	ELEP-1823	1.1.0	Occasionally, a RealPresence Debut system might shut down after sharing content or stopping content.	
User Interface	ELEP-2021	1.1.0	RealPresence Debut systems are unable to upload background images with non-English or special characters in the file name.	Ensure background image file names contain only English characters including: space, hyphen and alpha-numeric characters.
Video	ELEP-1914	1.1.0	In a call between a RealPresence Debut system and a Cisco 8710 TP, the far end video resolution is sometimes low for a few seconds.	

Get Help

For more information about installing, configuring, and administering Polycom products, refer to Documents and Downloads at [Polycom Support](#).

To find all Polycom partner solutions, see [Polycom Global Strategic Partner Solutions](#).

The Polycom Community

The [Polycom Community](#) gives you access to the latest developer and support information. Participate in discussion forums to share ideas and solve problems with your colleagues. To register with the Polycom Community, create a Polycom online account. When logged in, you can access Polycom support personnel and participate in developer and support forums to find the latest information on hardware, software, and partner solutions topics.

Copyright and Trademark Information

Copyright© 2016, Polycom, Inc. All rights reserved. No part of this document may be reproduced, translated into another language or format, or transmitted in any form or by any means, electronic or mechanical, for any purpose, without the express written permission of Polycom, Inc.

6001 America Center Drive
San Jose, CA 95002
USA

Trademarks Polycom®, the Polycom logo and the names and marks associated with Polycom products are trademarks and/or service marks of Polycom, Inc. and are registered and/or common law marks in the United States and various other countries.



All other trademarks are property of their respective owners. No portion hereof may be reproduced or transmitted in any form or by any means, for any purpose other than the recipient's personal use, without the express written permission of Polycom.

Disclaimer While Polycom uses reasonable efforts to include accurate and up-to-date information in this document, Polycom makes no warranties or representations as to its accuracy. Polycom assumes no liability or responsibility for any typographical or other errors or omissions in the content of this document.

Limitation of Liability Polycom and/or its respective suppliers make no representations about the suitability of the information contained in this document for any purpose. Information is provided "as is" without warranty of any kind and is subject to change without notice. The entire risk arising out of its use remains with the recipient. In no event shall Polycom and/or its respective suppliers be liable for any direct, consequential, incidental, special, punitive or other damages whatsoever (including without limitation, damages for loss of business profits, business interruption, or loss of business information), even if Polycom has been advised of the possibility of such damages.

End User License Agreement By installing, copying, or otherwise using this product, you acknowledge that you have read, understand and agree to be bound by the terms and conditions of the [End User License Agreement](#) for this product. The EULA for this product is available on the Polycom Support page for the product.

Patent Information The accompanying product may be protected by one or more U.S. and foreign patents and/or pending patent applications held by Polycom, Inc.

Open Source Software Used in this Product This product may contain open source software. You may receive the open source software from Polycom up to three (3) years after the distribution date of the applicable product or software at a charge not greater than the cost to Polycom of shipping or distributing the software to you. To receive software information, as well as the open source software code used in this product, contact Polycom by email at OpenSourceVideo@polycom.com.

Customer Feedback We are striving to improve our documentation quality and we appreciate your feedback. Email your opinions and comments to DocumentationFeedback@polycom.com.

Polycom Support Visit the [Polycom Support Center](#) for End User License Agreements, software downloads, product documents, product licenses, troubleshooting tips, service requests, and more.