

Release Notes

Polycom® HDX® Systems, Version 3.0.6



Polycom announces the latest release of Polycom HDX system software. This document provides the latest information about the following Polycom software:

- Version 3.0.6 of the Polycom HDX System software
- Version 1.5.0 of the Polycom Touch Control Operating System software
- Version 1.5.0 of the Polycom Touch Control Panel software

For more information about using the features described in this document, refer to the product documentation available for each Polycom HDX system at www.polycom.com/videodocumentation.



When making a connection from a web browser to configure the Polycom HDX system, always enter the address of the Polycom HDX system in one of the following formats: `https://hostname`, `https://10.11.12.13` or `https://2001:0:120:0:2e0:dbff:fe0d:3a26`.

If Security Mode is enabled on your system, you must use secure HTTPS access (for example, `https://10.11.12.13`). Click **Yes** in the security dialog boxes that appear.

Using the HTTPS protocol ensures that the configuration of all login credentials (such as user names and passwords) are transmitted using an encrypted channel, including those user names and passwords used to communicate with third-party systems on your network. Using the HTTPS protocol severely limits the ability of anyone on the network to discover these credentials.

Installing the Software

Procedures for installing Polycom HDX system software are different depending on whether the system is covered by warranty or a service plan. For more information about installing software updates, refer to *Installing Software and Options for Polycom HDX Systems and Accessories* at support.polycom.com.

Software Version History

Polycom HDX System Software

Software Version	Release Date	Description
3.0.6	May 2013	Security update for HDX system version 3.0.5
3.0.5	August 2012	Features added to obtain Microsoft® Lync® 2010 client qualification; support for connecting to Polycom SIP-based RealPresence solutions using Acme Packet Session Border Control (SBC); inclusion of software that supports a future release of the HDX 7000, hardware version D; introduction of the Polycom RealPresence® Resource Manager system
3.0.4	March 2012	Correction for issues related to customer escalations; enhancements to the Polycom UC Board application, which now allows you to save and retrieve content on a USB storage device
3.0.3.1	November 2011	Correction for issues related to Polycom Distributed Media Application™ (DMA™) failover support and to Brazilian conformance failures for Session Initiation Protocol (SIP) and H.323
3.0.3	October 2011	Improved integration with Microsoft Lync Server, which includes Call Admission Control; SIP Director and Failover support; RTV B-Frames encoding and CCCP Conference Control; improved SIP interoperability with POCN partners; Cisco TIP improvements; stronger media encryption keys in SIP & H.323; support for IPv6 Gatekeeper registration and calling; Bundled Provisioning; POST tests during boot-up; support for the UC Board annotation application; and security enhancements
3.0.2.1	August 2011	Correction for issues related to the HDX 4000 system privacy shutter, HDX system camera start up, Camera 2 video on HDX 6000 systems, and HDX systems registered to a SIP server
3.0.2	June 2011	Support for Telepresence Interoperability Protocol (TIP)
3.0.1	May 2011	Support for new EagleEye III and EagleEye Director, new HDX 4500 system; updated HDX system software
3.0.0.2	February 2011	Maintenance release that includes updates from software testing with Microsoft® Lync™ Server 2010
3.0.0.1	January 2011	Correction for an issue involving pairing an HDX system with a Polycom Touch Control
3.0	December 2010	Support for HDX systems and the Polycom Touch Control

Polycom Touch Control Software

Software Version	Description
1.5.0 Panel Software 1.5.0 Operating System	Support for a user to unpair from an HDX system
1.4.0 Panel Software 1.4.0 Operating System	Correction for displaying private meeting information on HDX systems
1.3.0 Panel Software 1.3.0 Operating System	Support for the Conference Composer feature in Centralized Conferencing Control Protocol (CCCP) and additional file types when showing USB content
1.2.0 Panel Software 1.2.0 Operating System	Support for USB content with the Polycom Touch Control (Experimental feature)
1.1.0 Panel Software	Support for EagleEye Director and Centralized Conferencing Control Protocol (CCCP)
1.0.3 Panel Software 1.0.3 Operating System	Support for Hardware Version 5 of the Polycom Touch Control and corrections for pairing issues
1.0.1 Panel Software	Corrections for pairing issues
1.0.0 Panel Software 1.0.0 Operating System	Initial release

Polycom EagleEye Director Software

Software Version	Description
1.0	Initial release

New Features in Version 3.0.6

The version 3.0.6 software includes the features and functionality of version 3.0.5, with the following additions.

HDX version 3.0.5 Security Update

This release contains security updates to the HDX version 3.0.5 software. Six security fixes are included:

[Security Bulletin 102404](#)

[Security Bulletin 107522](#)

[Security Bulletin 107523](#)

[Security Bulletin 107524](#)

[Security Bulletin 107525](#)

[Security Bulletin 107526](#)

To protect your Polycom HDX systems from malicious users, we strongly recommend that you install either HDX version 3.0.6 or 3.1.1.3.

Installation Scenarios

- If you have HDX version 3.0.x, you can install version 3.0.6; if you have entitlement to a software upgrade, you can install version 3.1.1.3.
- If you have HDX version 3.1.x, you can install version 3.1.1.3.
- If your HDX version is 3.0 or earlier, you must purchase a software upgrade or purchase a service contract which entitles you to upgrades.

You might want to install version 3.0.6 if you need additional time to test HDX version 3.1.1.3 software features, but also want to immediately deploy the latest security fixes. Version 3.0.6 software builds on version 3.0.5 by adding security enhancements introduced in version 3.1.1.3. Because version 3.0.6 does not include hot fixes based upon version 3.0.5, if you have version 3.0.5 which includes hot fixes, contact Polycom support for assistance.

Best Practices To Protect Your HDX Systems

To ensure that your HDX systems are secure from attacks, Polycom recommends the following best practices:

- Always use an Admin password on your videoconferencing systems. The password should not be easy to guess and of sufficient length that it cannot be discovered through brute force attempts. For guidance on creating strong passwords, refer to the *Administrator's Guide for Polycom HDX Systems*.

- Whenever possible, protect your HDX systems from unauthorized access by placing them inside your organization's network firewall.
- Carefully consider using Telnet on HDX systems. Disable Telnet if it is not required, particularly for systems accessible outside of the enterprise firewall on the internet. To assist in this decision, the following RealPresence features require Telnet:
 - Polycom SmartPairing™
 - Conferences scheduled with the Converged Management Application™ (CMA®) system
 - Telnet-based Integrator API applications
- If your HDX systems are used only when people are in a meeting room, disable **System > Admin Settings > General Settings > System Settings > Call Settings > Auto Answer** and also consider disabling the local camera's remote control.
- If you suspect that your system might have been compromised, we recommend that you use the Factory Restore method to install HDX system software.

More Information About Security Practices

For more information about any of these security practices, refer to the *Administrator's Guide for Polycom HDX Systems*. For the latest information about Polycom products and security, go to <http://www.polycom.com/security> and click **Polycom Security Center**.

New Features in Version 3.0.5

The version 3.0.5 software includes the features and functionality of version 3.0.4, with the following additions.

Microsoft® Lync® 2010 Feature Enhancements

HDX system software version 3.0.5 adds functionality required to achieve Microsoft® Lync® 2010 client qualification. The specific features being added or enhanced are described in the following sections. These features are supported in both Microsoft Lync 2010 server and Microsoft Office Communications Server 2007 R2 environments.

Media over TCP

This feature adds support for processing TCP ICE candidates and then transporting real-time media streams over the TCP connection when UDP sockets are blocked. Calls can now connect in environments where firewall administrators limit access to only TCP ports.

Call Hold, Call Resume

When an HDX system is registered to a Microsoft Lync server, the HDX system can participate in Lync-hosted multipoint calls. You can now use hold and resume features on the HDX system when it is in certain types of Lync-hosted calls.

Forward Error Correction for Real-Time Video

HDX system software version 3.0.5 extends Real-Time Video (RTV) support, which minimizes the appearance of visible defects in the video image under conditions where packets are being lost in the network.

DTMF Support in Microsoft Server Environments

This feature adds support for passing DTMF tones in calls made within a Microsoft server environment.

Long Duration Call Support

This feature supports call durations up to 24 hours in Microsoft server environments.

Basic Firewall/NAT Traversal Connectivity

This feature allows HDX systems to connect to the SIP-based RealPresence solutions using Acme Packet SBC in certain scenarios.



The HDX system requires the use of an access server deployed on the edge of the enterprise network to use Acme Packet SBC.

In addition to enabling SIP keep-alive messages on the HDX system's web interface, the Firewall/NAT traversal feature supports using the installed client certificate on SIP and XMPP connections.

Polycom RealPresence® Resource Manager

HDX system software version 3.0.5 supports the Polycom RealPresence® Resource Manager system, which is conference management software that can take the place of the CMA system. RealPresence Resource Manager provides the same capabilities to HDX systems as the CMA system does, except that the Polycom® Distributed Media Application™ (DMA™) system has assumed the

gatekeeping responsibilities previously held by the CMA system. Users and administrators will see no interruption of service resulting from DMA systems becoming the gatekeepers for HDX systems.

Polycom HDX 7000 Systems with Hardware Revision D

HDX system software version 3.0.5 adds support for the HDX 7000 series system with Hardware version D. The HDX 7000 series systems will not include S-Video output connectors on the back panel. With these HDX 7000 series systems, you will no longer be able to use S-video to record meetings, but you can still use the DVI breakout cable to record composite video out. You can also consider using Polycom RSS™ 4000, which is a web server that enables you to easily perform recording, live streaming, stream media processing, and multimedia archiving.

HDX 7000 series systems must run Polycom HDX system software version 3.0.5 or later.

MusicMode

The Live Music Mode feature is now named MusicMode. There is no change in the functionality.

Polycom Solution Support

Polycom Implementation and Maintenance services provide support for Polycom solution components only. Additional services for supported third-party Unified Communications (UC) environments integrated with Polycom solutions are available from Polycom Global Services, and its certified Partners, to help customers successfully design, deploy, optimize, and manage Polycom visual communication within their third-party UC environments. UC Professional Services for Microsoft® Integration is mandatory for Polycom Conferencing for Microsoft Outlook and Microsoft Office Communications Server or Microsoft Lync™ Server integrations.

For additional information and details please refer to [Professional_services/index.html](#) or contact your local Polycom representative.

Hardware and Software Compatibility

The following table lists HDX system software versions that are compatible with Polycom hardware.

Hardware Model	Designation in User Interface	Part Number (or Serial Number)	Compatible Software Versions (see Notes)	Real-Time Clock
Polycom HDX 4000	—	2201-24657-XXX 2215-24647-XXX	2.0.1 or later (but not 2.0.3.2 or 2.5)	No
Polycom HDX 4000 HD	—	2201-24176-XXX 2215-24646-XXX	2.0.1 or later (but not 2.0.3.2 or 2.5)	No
Polycom HDX 4000 HD	Rev C	2201-12698-XXX 2215-12699-XXX	2.7.0J, 3.0 or later	Yes
Polycom HDX 4500	—	2201-61845-XXX 2215-09830-XXX	3.0.1 or later	Yes
Polycom HDX 6000 HD	—	2201-28619-XXX 2215-28711-XXX	2.5.0.6 or later	Yes
Polycom HDX 7000	—	2201-27285-XXX 2215-27427-XXX	2.0.2 or later (but not 2.5)	No
Polycom HDX 7000	—	2201-28629-XXX 2215-28632-XXX	2.5.0.1 or later	Yes
Polycom HDX 7000 HD	Hardware Version A (running 2.5.x or later versions of software, blank with earlier versions)	2201-27284-XXX 2215-27426-XXX	2.0.2 or later (but not 2.0.3.2 or 2.5)	No
Polycom HDX 7000 HD	Hardware Version B	2201-28128-XXX 2215-28127-XXX	2.5.0.1 or later	Yes
Polycom HDX 7000 HD	Hardware Version C	2201-26773-XXX 2215-26771-XXX	2.5.0.7 or later	Yes
Polycom HDX 7000	Hardware Version D	---	3.0.5 or later	Yes
Polycom HDX 8000 HD	Hardware Version A (2.5.x or later versions of software, blank with earlier versions)	2201-24506-XXX 2215-24614-XXX	2.0 or later (but not 2.0.0J, 2.0.3.2, or 2.5)	No
Polycom HDX 8000 HD	Hardware Version B	2201-27951-XXX 2215-27952-XXX	2.5.0.1 or later	Yes

Hardware Model	Designation in User Interface	Part Number (or Serial Number)	Compatible Software Versions (see Notes)	Real-Time Clock
Polycom HDX 9001	—	2201-23784-XXX 2201-23795-XXX 2215-23796-XXX 2201-28218-XXX	2.0.0J, 2.0.2 or later (but not 2.0.3.2 or 2.5)	Yes
Polycom HDX 9002	—	2201-23783-XXX 2201-23782-XXX 2215-23788-XXX 2201-28217-XXX 2215-23788-XXX 2201-29004-XXX	2.0.5J or later (but not 2.5 or 2.5.0.1)	Yes
Polycom HDX 9004	—	2201-23722-XXX 2201-23283-XXX 2215-23358-XXX 2201-28216-XXX 2215-23358-XXX 2201-29006-XXX	2.0.0J and 2.0.2 or later (but not 2.0.3.2, 2.5, or 2.5.0.1)	Yes
Polycom HDX 9006	Hardware Version B	2201-32806-XXX 2215-61826-XXX	2.6 or later	Yes
<p>Notes:</p> <ul style="list-style-type: none"> The column “Compatible Software Versions” shows the approved/qualified software versions. Software Update enforces most of these rules. Systems that do not have a real-time clock will not retain the time of day across reboots. They should be configured to use an NTP server. 				

Corrected Issues in Version 3.0.5

The following table lists issues corrected in version 3.0.5.

Category	Jira ID	Description
Cameras	VIDEO-95454	When the HDX 4500 desktop system is reset, the camera position and zoom might not return to the Preset 0 position. This problem has been corrected.
Cameras	VIDEO-95455	After panning for several seconds, the MPTZ-9 camera might display poor quality video. This problem has been corrected.
Content	VIDEO-95485 VIDEO-94927	On HDX 7000 and 8000 room series systems, users could not send high frame rate content. This problem has been corrected.
Content	VIDEO-79181	When the resolution was configured for 1280x720 on a laptop connected to an HDX 9000 series system, the HDX system would not display content correctly. This problem has been corrected.
Directory	VIDEO-95453	Your call might fail when dialing a directory entry when the IP address and phone extension are in separate fields and the HDX system is not registered to a gatekeeper. This problem has been corrected.
Directory	VIDEO-95468	If a directory entry only includes an extension, the Polycom Touch Control cannot dial the call. This problem has been corrected.
Directory	VIDEO-95509	The Polycom Touch Control and HDX system did not display directory entries from a Microsoft Lync Server that contained more than 20,000 entries. This problem has been corrected.
Directory	VIDEO-96526	Changes made to a global directory are seen in the web interface but not in the Polycom Touch Control directory. This problem has been corrected.
Documentation	VIDEO-94635	The User's Guide for HDX systems and the Polycom Touch Control is incorrect. To enter an asterisk, press the Video button and then press the asterisk button (*) on the SoundStation IP 7000 keypad two times. This problem has been corrected.
Interoperability Cisco	VIDEO-95460	After connecting to an HDX system over SIP, the Cisco TelePresence Edge95 system would restart. This problem has been corrected.
Interoperability Cisco	VIDEO-95371	Video and audio issues occurred when HDX systems interoperated with Cisco Telepresence Systems (CTS) version 1.8.x. This problem has been corrected.
Interoperability Cisco	VIDEO-96525	An HDX 4000 series system registered with Cisco VCS (V.6) as SIP registrar is unable to connect SIP calls. This problem has been corrected.
Interoperability Microsoft	VIDEO-88126	When an HDX system was registered to a Microsoft Office Communications Server or a Microsoft Lync Server, the system would falsely indicate that it could receive instant messages when it could not. This problem has been corrected.

Category	Jira ID	Description
Interoperability Microsoft	VIDEO-94331	When placing analog phone calls, HDX systems integrated with Microsoft Lync do not automatically add a 1 to the dial string. This problem has been corrected.
Interoperability Microsoft	VIDEO-94804	When an HDX system searched for a name in a Lync address directory with more than 20,000 addresses, this error message displayed: "The directory server is unable to process your request. Please try again or contact your system administrator for assistance." This problem has been corrected.
Interoperability Microsoft	VIDEO-95451	When you schedule a meeting using Microsoft Lync Online Meeting, the Join Now icon might not appear. This problem has been corrected.
Interoperability Microsoft	VIDEO-95467	When ICE is enabled on an HDX system with 3.0.3.1 software, the HDX system cannot receive an audio call through the Microsoft Lync Gateway. This problem has been corrected.
Interoperability Microsoft	VIDEO-95483	If Microsoft Outlook is set to the German language, the HDX system does not display the Join Now button for the user to join the Lync online meeting. This problem has been corrected.
Interoperability Microsoft	VIDEO-96522	For HDX systems in a Lync environment, the directory was not searchable on the HDX system. This problem has been corrected.
Interoperability Polycom Converged Management Application™ (CMA®) Desktop (CMAD)	VIDEO-95554	Content could not be viewed by all participants when an HDX system was hosting a conference with two or more CMA Desktop clients and the content token was sent to another CMA Desktop system. This problem has been corrected.
Interoperability Polycom RMX System	VIDEO-95464	A pillar box effect sometimes occurs on HDX system calls from a RMX system. This problem has been corrected.
Interoperability Polycom Touch Control	VIDEO-95470	On a Polycom Touch Control connected to an HDX 7000 series system, when you select content you cannot choose a PC icon. The only option is DVD. This problem has been corrected.
Interoperability Polycom Touch Control	VIDEO-96523	The HDX system was unable to send content while paired with Polycom Touch Control. This problem has been corrected.
Interoperability Polycom Touch Control	VIDEO-97731	The Polycom Touch Control does not display call statistics of a Lync Online Meeting, during calls with CCCP and RTV options enabled and Polycom Touch Control is paired with an HDX system. Polycom Touch Control statistics columns appear as blank. But, Web UI displays the statistics, as expected. This problem has been corrected.
Interoperability Polycom Touch Control	VIDEO-97821	On some ITP systems, buttons on the Polycom Touch Control admin page do not toggle properly. This problem has been corrected.

Category	Jira ID	Description
Interoperability Polycom Touch Control	VIDEO-97886 VIDEO-95985 VIDEO-96196	Polycom Touch Control directory searches return a limited set of search results or no results. This problem has been corrected.
Interoperability Polycom Touch Control	VIDEO-97889	Polycom Touch Control software can be updated automatically but there is no mechanism to update the HDX system software automatically, which causes the HDX system and Polycom Touch Control to become unpaired. This problem has been corrected.
Interoperability Polycom Touch Control	VIDEO-98137	After hanging up a point-to-point call using Polycom Touch Control, the Polycom Touch Control jumps to the In Call screen which displays "Calling...". The screen continues to display "Calling..." even when the system is no longer in a call. This problem has been corrected.
Interoperability Polycom VSX Systems	VIDEO-94377	When connecting to a VSX system, an HDX 6000 room series system intermittently failed to request Open Logic Channel (OLC) for H.263 content. This problem has been corrected.
Interoperability Polycom VSX Systems	VIDEO-95469	On HDX systems, RMX system chairperson announcements might have had audio issues. This problem has been corrected.
Interoperability Polycom VSX Systems	VIDEO-95479	When an HDX system hosts an internal CP MCU call, the MCUs near site video displays an incorrect aspect ratio when a VSX system connects to the call. This problem has been corrected.
Interoperability Polycom VSX Systems	VIDEO-95481	If an HDX system hosts an internal CP MCU call with two other HDX systems and the VSX system joins last, the top L and R quadrants display an incorrect aspect ratio. This problem has been corrected.
Interoperability RADVISION	VIDEO-95458	HDX systems did not transmit video to RADVISION via IP. This problem has been corrected.
Interoperability RADVISION	VIDEO-95473 VIDEO-94788	When connecting to a RADVISION Pathfinder system with H.460.19 Media Multiplex support, HDX systems might restart. This problem has been corrected.
Multipoint	VIDEO-97887	During Multipoint calls, the HDX system spontaneously reboots when making a SIP call connected to a H.323 device and a PSTN call through LYNC mediation server/PSTN GW. This problem has been corrected.
Network	VIDEO-95459	When calling annex O addresses, HDX systems do not include the entire @domain string to complete the call. This problem has been corrected.
Network	VIDEO-95472	HDX systems restart and disconnect from H.323 calls due to SIP-related network issues. This problem has been corrected.
Provisioning	VIDEO-86491	In some environments, the Recent Calls button might disappear from the HDX system's Home screen after CMA v5 configures a system using scheduled provisioning. This problem has been corrected.

Category	Jira ID	Description
Provisioning	VIDEO-95456	Dynamically managed HDX systems in a Microsoft Lync environment do not correctly report Directory or Presence status to the Polycom CMA server. This problem has been corrected.
SIP	VIDEO-95502	With some LDAP queries, the HDX system is unable to dial entries with SIP addresses. This problem has been corrected
SIP	VIDEO-97278	Latency is not being calculated when making SIP calls. Latency is reported in the CDR for H.323 but it never reported for SIP. This problem has been corrected
SNMP	VIDEO-76856	HDX systems did not issue an SNMP alert for excessive Jitter or Latency in a call. This problem has been corrected.
User Interface	VIDEO-95471	On HDX 4500 desktop systems, no display option checkboxes were available in the Dual Monitor setting. This problem has been corrected.
User Interface	VIDEO-95477	After you disconnect a call and are asked if you want to add the number to the directory, the message disappears too soon. This problem has been corrected.
User Interface	VIDEO-95486	When a custom banner is enabled in the user interface, all lines of text under the security banner are not legible. This problem has been corrected.
User Interface	VIDEO-96519 VIDEO-94218 VIDEO-93894	The UI became sluggish, with delayed Mute and call Hang up and occasional frozen video. Excessive authentication requests were causing issues with system performance. A temporary workaround is to turn on Enable Sessions List . As a result of this workaround, the Maximum Number of Sessions Per Users allowed has been increased to 25. Authentication cookie support will be added in a future release.
Video	VIDEO-95461	The HDX 7000, 8000, and 9000 series room systems display poor quality video on S-Video monitor output 3. This problem has been corrected.
Web Interface	VIDEO-95452	The Sample Sites entry cannot be removed from the directory list in the web interface. This problem has been corrected.
Web Interface	VIDEO-95457	HDX systems are unable to answer ISDN voice and analog phone calls through the web interface. This problem has been corrected.
Web Interface	VIDEO-95465	The SIP URL address appears in the Name field instead of the Favorites name in the web interface. This problem has been corrected.
Web Interface	VIDEO-95482	In the web interface, if you select Update to change the time zone or to enable or disable StereoSurround while in a call, the update is not applied and you are unable to move to the next screen. This problem has been corrected.
Web Interface	VIDEO-96521	The web interface Diagnostic screen referred to the Call Status page instead of "Call Statistics." This problem has been corrected.

Known Issues

The following table lists the known issues for the version 3.0.5 release. If a workaround is available, it is noted in the table.

Category	Issue ID	Found in Release	Description	Workaround
Active Directory Server	VIDEO-85246	3.0	Setting the Security Profile to Maximum during the Setup Wizard causes External Authentication to be enabled. Although administrators can create local user IDs and passwords, local users will not be able to access the HDX system as long as External Authentication is enabled.	After you complete the Setup Wizard, go to System > Admin Settings > General Settings > Security > External Authentication and disable the Enable Active Directory Authentication setting to enable local users to access the system.
Analog Phone	VIDEO-80791	2.6	Incoming calls from analog phones do not display on the Recent Calls screen.	
Analog Phone	VIDEO-73949	2.5.0.4	Do not use the analog phone connector if you are using as HDX 9000 series system in Hong Kong or South Africa. If your HDX 9000 series system came with a telephone adapter, refer to the accompanying telephone adapter setup sheet for information on whether the adapter is needed in your area.	
API	VIDEO-95475	2.6.1.3	The API command <i>answer phone</i> does not always return feedback.	
API	VIDEO-95466	3.0.4	When using a <i>camera near</i> API command and switching back to camera 1, auto-tracking is not re-enabled.	
API	VIDEO-51280	1.0	The <i>remotecontrol enable all</i> command does not work after disabling the remote. Use <i>remotecontrol disable none</i> to enable the remote control buttons.	

Category	Issue ID	Found in Release	Description	Workaround
API	VIDEO-55286	1.0.2	<pre>state[ALLOCATED] cs: call[38] chan[0] dialstr[172.26.48.42] state[RINGING] cs: call[38] chan[0] dialstr[172.26.48.42] state[BONDING] cs: call[38] chan[0] dialstr[172.26.48.42] state[COMPLETE] active: call[38] speed[512]</pre> <p>The notification in boldface is not applicable to calls made to and received from IP end points.</p>	
API	VIDEO-97277	3.0.5	API command: unexpected successful response for "vcraudioout" commands on HDX 7000 Rev D.	
Audio	VIDEO-55634	1.0.1	If you establish multiple calls between the two systems, you may experience audio feedback.	
Audio	VIDEO-60669	2.0	Incoming voice calls do not work in a password-protected conference.	
Audio	VIDEO-70543	2.5	When you plug a headset into the HDX 4000 series system panel, the system's built-in microphones and any attached microphones are automatically muted even though the Enable Polycom Microphones and Enable Built-In Microphones configuration settings remain selected.	
Audio	VIDEO-69705	2.5	Starting with the release 2.5, HDX systems do not play music while restarting. HDX systems running software version 2.6 play an announcement tone once the system has been successfully restarted.	

Category	Issue ID	Found in Release	Description	Workaround
Audio	VIDEO-69796	2.5	You cannot enable or disable Stereo while in a call.	
Audio	VIDEO-69797	2.5	Do not connect or disconnect a Polycom SoundStation IP 7000 conference phone or HDX system digital microphones while in a call. Doing so may result in some anomalous behavior such as audio coming out both the conference phone and HDX system. To restore normal operation, hang up the call.	
Audio	VIDEO-71505	2.5.0.1	Volume changes made during the setup wizard are lost when the system restarts.	
Audio	VIDEO-97677	-	When the Polycom StereoSurround setting is enabled on HDX 4000 series systems, audio might drop during a call that connects to a Virtual Meeting Room (VMR) through the Polycom Halo H.323 Meet-Me Service. Polycom Halo H.323 Meet-Me Service users must disable the Enable Polycom StereoSurround setting in HDX 4000 series systems by navigating to Admin Settings > Audio Settings.	
Calling	VIDEO-91639	3.0.2	During multipoint video conference calls using the Lync Server, the video conference session might not completely disconnect when the Organizer disconnects from the conference. This behavior depends upon how Meeting Policies are configured on the Lync Server, and might be observed when the Lync Client is the organizer or when the HDX system is the organizer.	
Calling	VIDEO-78158	2.6	Meeting passwords are not supported in SIP calls.	Use H.323 for calls that require meeting passwords.

Category	Issue ID	Found in Release	Description	Workaround
Calling	VIDEO-51286	1.0	Calls dialed using analog voice lines will not roll over to other call types if the call is busy or otherwise fails.	
Calling	VIDEO-51323	1.0	Do not mix unrestricted (speeds that are a multiple of 64 kbps) and restricted (multiple of 56 kbps) participants in an internal multipoint conference.	
Calling	VIDEO-70792	2.5	Do not use H.323 names that include a comma.	
Calling	VIDEO-76492	2.5.0.6	Calls do not connect if the HDX system is not restarted after changing ISDN settings. To avoid this issue, restart the HDX system any time an ISDN parameter is changed.	
Calling	VIDEO-80193	2.6	When an HDX system hosting a multipoint call is connected to the maximum number of video endpoints, the Place A Call screen displays Add Video Call instead of Add Audio Call. The HDX system will be able to connect to an additional audio endpoint, but will not be able to connect to another video endpoint.	
Calling	VIDEO-88199	3.0	HDX systems using call rates of 2x56 kbps or 2x64 kbps might fail to connect V.35 calls.	Use a call rate of 1x112 kbps or 1x128 kbps.
Calling	VIDEO-97503	3.0.3.1	When Admin Setting (General > System > Call Settings) is set to 'Auto Answer/Point to Point / Do Not Disturb', audio transmitted from the far end can be heard both through the IP7000 speakers and the HDX speakers, simultaneously.	
Calling	VIDEO-98104	3.0.5	During MCU calls to 3 remote sites, the two SIP calls remain connected at 6144Kbps and 1024Kbps, respectively. But the third ISDN call crashes (intermittently) at 6144Kbps	

Category	Issue ID	Found in Release	Description	Workaround
Calling	VIDEO-98136	-	The ' <i>mpautoanswer donotdisturb</i> ' command sets the HDX system to Do Not Disturb both in and out of calls. The command is supposed to place the HDX system in the Do Not Disturb state only when it is already in a call.	
Calling	VIDEO-98245	3.0.5	Customers may experience a crash when placing a Point-to-Point call from an HDX system that is registered to a SIP server with a DMA IPv4 address to a Far End HDX system that is registered to a SIP server with a DMA IPv6 address.	Disable H.239 for improved customer experience.
Cameras	VIDEO-95512	3.0.3.1	An MPTZ-9 camera on an HDX system is compared unfavorably to a EagleEye II camera because of video noise.	EagleEye II cameras provide higher quality video than MPTZ-9 cameras.
Cameras	VIDEO-80258	2.6	The only supported camera for the HDX 4000 series system is part of the video screen that is shipped with the HDX 4000 series system. If a different camera is connected to the HDX 4000 system, the HDX 4000 system will turn off (if powered on) or will not power on if in a powered off state.	Remove the unsupported camera and reconnect the video screen that was shipped with the HDX 4000 series base system.
Cameras	VIDEO-80077	2.5	The HDX system enables you to select a 4:3 aspect ratio when an EagleEye Director is selected, even though it is not a supported aspect ratio. The HDX system will automatically default to the supported 16:9 aspect ratio without informing the user that the 4:3 aspect ratio was not a supported resolution.	
Cameras	VIDEO-80255	2.6	When an HDX 4000 series system is in a call, pressing the 0 button does not move the HDX 4000 series camera to the default camera preset 0.	Manually adjust the camera to the desired position.

Category	Issue ID	Found in Release	Description	Workaround
Cameras	VIDEO-80582	2.6	Far-end camera control is not supported when in a multipoint call.	
Cameras	VIDEO-51830 VIDEO-52304 VIDEO-80196	1.0	You may see blue video for a few seconds while the HDX system camera wakes up. The camera may also take a few seconds to focus after waking up.	
Cameras	VIDEO-59339	2.0	If you downgrade the software to a version earlier than 2.0, you may need to reconfigure white balance on the EagleEye HD camera.	Select the detect camera command in the user interface or web interface, and then configure the white balance.
Cameras	VIDEO-97527	3.0.5	The HD 8006 system only shows 2nd Camera info in System Information from WEB UI and TV UI.	
Cameras	VIDEO-71003	2.5	If you have an external power supply attached to a camera and you want to move that camera from one port to another, you must follow these steps: <ol style="list-style-type: none"> 1 Power off the camera. 2 Connect the camera to the new port. 3 Power on the camera. 4 Select Detect Camera in the system's user interface. 	
Cameras	VIDEO-81290	2.5	When an EagleEye 1080 camera is attached to an HDX system, you can select a 4:3 aspect ratio, which will result in video stretched vertically with black bars on the side of the video.	Select an aspect ratio of 16:9.

Category	Issue ID	Found in Release	Description	Workaround
Cameras	VIDEO-82747	2.5.0.4	The camera name can be modified only with Roman-based characters. If you modify the camera name using non-Roman-based characters, a message displays instructing you to use valid characters on the keyboard. Trying to modify the camera name with non-Roman-based character results in the camera name disappearing.	Use Roman-based characters only when modifying the camera name.
Cameras	VIDEO-84040	2.6.1	When an EagleEye View camera is connected to an HDX system, the Power Frequency drop-down menu is shown on the Cameras Settings page. The Power Frequency drop-down menu is not applicable for the EagleEye View camera.	
Cameras	VIDEO-84272	2.6.1	The Backlight Compensation setting is not applicable when an EagleEye 1080 camera is connected as the main camera and the Power Frequency setting is set to 50Hz, even though the Backlight Compensation check box is not grayed out.	
Cameras	VIDEO-84274	2.6.1	When an EagleEye View camera is connected to an HDX system, the Camera Settings page displays the Backlight Compensation setting. As backlight compensation is not applicable to a EagleEye View camera, this setting should not be displayed.	
Cameras	VIDEO-90458	3.0.1	The EagleEye Director does not support the People on Content Feature.	Use alternative cameras.

Category	Issue ID	Found in Release	Description	Workaround
Cameras	VIDEO-90460	3.0.1	Depending on where people are sitting in relation to the EagleEye Director, two people who sit close together and take turns talking over a period of time might not be correctly framed together by the camera.	
Cameras	VIDEO-90461	3.0.1	If a Room View adjustment or camera calibration is taking place, the EagleEye Director will not send or will stop sending content. Users can send content after the adjustment or calibration is completed.	
Cameras	VIDEO-90462	3.0.1	When the EagleEye Director is in a point-to-point or multipoint call with an RMX 2000/4000 series system, version 7.2, the switch between People View and Room View causes flashes of white video on the far side.	Turn off the Auto Brightness setting on the RMX2000/4000 series system.
Cameras	VIDEO-90463	3.0.1	In sleep mode, the EagleEye Director does not go to the back-facing positions.	
Cameras	VIDEO-90465	3.0.1	If the EagleEye Director is focused on a speaker with another person in the frame, in either foreground or background, EagleEye Director will not focus on the second person if he or she begins speaking immediately after the first speaker.	Ensure that adequate spacing exists between people in the room, or have speakers who are close together wait until EagleEye Director refocuses on the room before having the second person begin talking.
Cameras	VIDEO-90467	3.0.1	The EagleEye Director has a range of approximately 10 feet, or 3 meters, when it has panned to a 90-degree angle. People located at the extreme of this range might not always be recognized by the tracking feature, and therefore the camera may not focus on them as they speak.	Ensure that all speakers are located well within the camera's range.

Category	Issue ID	Found in Release	Description	Workaround
Cameras	VIDEO-90468	3.0.1	If a factory restore function is performed on the EagleEye Director, the version of software shown will be the same as before the factory restore was done, even though the camera has returned to the software load with which it was provisioned.	Have the HDX system redetect the EagleEye Director, and check the software version from the HDX system. Both the EagleEye Director and the HDX system will now report the correct software version.
Cameras	VIDEO-90469	3.0.1	The EagleEye Director draws green lines on the screen to perform calibration. If the HDX system restarts while the EagleEye Director is calibrating, the green lines will still be present after the HDX system restarts.	To remove the green lines, either go to the EagleEye Director calibration page again, or restart the EagleEye Director.
Cameras	VIDEO-90470	3.0.1	An EagleEye Director close-up shot may appear off-center when displayed in 4:3 aspect ratio.	Set the HDX system People Video Adjustment to None or Stretch on all HDX systems in the call.
Certificates	VIDEO-86209	3.0	If certificates are installed, you might get a <i>Page Cannot Be Displayed</i> message after manually changing the date or time.	Restart the HDX system after you manually change the date or time.
Chair Control	VIDEO-80896	2.6	When a system acting as chair control selects an endpoint and selects the View Site icon, the endpoint's video will be shown but the web interface will provide a status of <i>denied</i> .	
Chair Control	VIDEO-80895	2.6	When a system acting as chair control selects an endpoint and selects the View Site icon, the endpoint's video will be shown. When the system with chair control selects the Stop Viewing Site icon, the web interface provides a status of <i>denied</i> but the endpoints video is no longer displayed.	

Category	Issue ID	Found in Release	Description	Workaround
Chair Control	VIDEO-80897	2.6	When a system acting as chair control selects the Disconnect Site icon to disconnect an endpoint from a conference, the web interface returns a status of <i>denied</i> , even though the endpoint was disconnected from the conference.	
Chair Control	VIDEO-74353	2.5.0.4	When selecting a system to have chair control, the endpoint does not stay highlighted as being the chair control. To release chair control, highlight all the participants in the Meeting Participants window and select Release Chair .	
Closed Captions	VIDEO-59615	2.0	When providing closed captions over a serial connection, you must manually go to near video before entering text.	
Closed Captions	VIDEO-60912	2.0	Closed captioning (sent through either the serial port or the web interface) is limited to 31 characters per line.	
Contacts	VIDEO-70317	2.5	HDX systems can share presence information with up to 200 Contacts. If a remote site attempts to invite the HDX system as a Contact after it has reached its limit of 200 Contacts, the HDX system rejects the invitation but does not display a warning message to the local user.	
Contacts	VIDEO-68749	2.5	You cannot delete Contacts using the web interface.	Instead, delete them in the system's local interface.
Content	VIDEO-51633	1.0	Some DVI video sources (such as certain laptops) do not correctly support the hot plug detect pin (HPD). This can result in the source sending video in the wrong format for HDX system video input ports 4 and 5. Please consult your equipment manuals to find out the behavior of the HPD pin.	

Category	Issue ID	Found in Release	Description	Workaround
Content	VIDEO-55041	1.0.2	Presets support switching from one People source to another. Presets do not support switching from a People source to a Content source or from one Content source to another.	
Content	VIDEO-58577	2.0.5.4	Content at a resolution of 1280 x 1024 is scaled and sent to the far site in 1024 x 768 format unless the far site can display it at 1280 x 1024.	
Content	VIDEO-59132	2.0	You cannot send content from an HDX 4000 series system using the Content button on a HDX system remote control.	You must use the built-in keypad button.
Content	VIDEO-70799	2.5	When hosting a multipoint call, HDX systems typically stop showing content when a new participant joins the call. It may fail to do so when the fourth participant joins.	
Content	VIDEO-81293	2.5.0.5	If the Quality Preference setting on the Cameras screen is configured for content and a call is placed at 6 Mbps, the allocated bandwidth for content is only 1.5 Mbps.	
Content	VIDEO-75994	2.5.0.6	Occasionally, an HDX 9000 series system will not show content when a computer connected directly to the HDX system is coming out of sleep mode.	Stop the content and resend it.
Content	VIDEO-98160	3.0.5	H.320 endpoints connected to RMX system conferences do not receive content from HDX systems connected via SIP to the same RMX system conference when the connection rates differ significantly between the HDX and the H.320 endpoints.	Lower the connection speed of the HDX system connected via SIP to match the connection rate of the H.320 endpoints.
Directory	VIDEO-61245	2.0.1.1	When a directory entry has both an ISDN and IP address, calls placed as IP connect at the designated call rate for ISDN.	

Category	Issue ID	Found in Release	Description	Workaround
Directory	VIDEO-65729	2.0.5_J	An entry in a custom directory group may be removed from the group if you edit the entry. The entry is still available in the Contacts group.	
Directory	VIDEO-70647	2.5	From time to time a directory query may not return a full list of matching entries.	Reissue the request.
Directory	VIDEO-76896	2.5.0.7	If the HDX system is downgraded to a version earlier than 2.5.0.x and new directory groups are created, the groups will not be retained in subsequent upgrades.	
Encryption	VIDEO-77204	2.5.0.7	When an unencrypted HDX system calls into an encrypted call between a TANDBERG MXP system and a Sony PCS-G50 system, the HDX system will connect but the Sony system will hear loud, distorted audio.	Enable encryption on the HDX system.
Factory Restore	VIDEO-80175	2.6	When performing a factory restore on an HDX 9000 series system, green video is displayed for a few seconds before the system restarts. This is normal behavior and the system will boot to the setup wizard.	
Gatekeepers	VIDEO-95510	3.0.3	Due to a missing <i>refresher</i> parameter, HDX systems do not respond to 200 OK messages from a System Architecture Evolution (SAE) media gateway.	
Gatekeepers	VIDEO-60344	2.0	Registering to a gatekeeper may change the dialing order configured on the system.	

Category	Issue ID	Found in Release	Description	Workaround
Hardware	VIDEO-93328	3.0.1	Field-upgraded hardware does not function correctly if restored to a factory partition with software that is not recent enough to support it. For example, upgrade kits for HDX 7000 and 8000 series systems require software version 2.5.0.7 or later. HDX 4000 series upgrade kits require version 3.0 or later.	Contact your Polycom representative or customer support to ensure that the factory partition contains a software version that supports the upgraded hardware.
Hardware	VIDEO-80075	2.5.0.5	HDX systems with a QBRI card installed do not issue an SNMP alert when the QBRI card is replaced with a PRI card.	
Hardware	VIDEO-80072	2.5.0.5	HDX systems do not issue an SNMP alert when a V.35 card is installed or uninstalled	
Hardware	VIDEO-82738	2.6	HDX systems restart when the HDX system microphone cable is connected incorrectly.	Connect the HDX system microphone cable correctly.
Hardware	VIDEO-98155	3.0.2	Intermittently, HDX systems customers may experience an HDX 7000 series system rebooting automatically during a conference. When this occurs, all configurations of the HDX 7000 series system are lost. However, after reconfiguring the HDX system, the conference continues.	
ICMP	VIDEO-86436	3.0	The ICMP Transmission Rate Setting on the LAN Properties screen applies only to "error" ICMP packets. This setting has no effect on "informational" ICMP packets, such as echo requests/replies.	
Interoperability Cisco	VIDEO-95620	3.0.4	When connecting to a Cisco TelePresence 3010 system, Polycom® OpenTelePresence Experience™ (OTX) systems might take 90 seconds or more before showing video on the center screen.	

Category	Issue ID	Found in Release	Description	Workaround
Interoperability Cisco	VIDEO-94999	3.0.4	When an HDX system dials into Cisco Unified Videoconferencing (CUVC) through H.323, it does not receive content from Cisco TelePresence System (CTS).	
Interoperability DMA	VIDEO-93525	3.0.3	When a VVX 1500 business media phone and two HDX endpoints are registered to a DMA system's SIP server, a video call initiated from the VVX 1500 phone to the first HDX system gets disconnected after the VVX 1500 phone tries to transfer the call to the second HDX system, which also gets disconnected.	
Interoperability LifeSize	VIDEO-86789	3.0	Calls between HDX systems and Lifesize Room Systems over IPv6 do not connect when both systems are configured for maximum security.	
Interoperability Microsoft	VIDEO-95478	3.0.3.1	The Polycom Touch Control cannot retrieve the Favorites list or directory entries from the OCS 2007 R1 Edge server because OCS 2007 R1 is no longer supported.	
Interoperability Microsoft	VIDEO-95476	3.0.3	You cannot add a third participant to an AV/MCU-based Lync CCCP call when the Enable PSTN dial-in conferencing setting is disabled.	
Interoperability Microsoft	VIDEO-95370	3.0.4	Incompatible Windows NT LAN Manager (NTLM) settings might cause an HDX system reset. This issue occurs when the Server Authentication Level is set to Send NTLMv2 response only, and Refuse LM, NTLM, and the HDX system is set to NTLMv1.	Set the HDX system NTLM setting to Auto or NTLMv2.

Category	Issue ID	Found in Release	Description	Workaround
Interoperability Microsoft	VIDEO-94943	3.0.1	When using external authentication such as Active Directory, ensure that the local admin account is password protected. You should also enable Require Login for System Access and set a user password.	
Interoperability Microsoft	VIDEO-93528	3.0.3	When using Microsoft Office Communications Server 2007 or Microsoft Lync Server 2010 as your global directory, if you search for a common last name, the HDX system might return the first 200 matches without giving any warning that there might be more matches.	
Interoperability Microsoft	VIDEO-91317	3.0.1	HDX systems do not support public switched telephone network (PSTN) calls on the Mediation Server Gateway in a Microsoft OCS or Microsoft Lync Environment.	To make a PSTN call, append "+" before the number to dial.
Interoperability Microsoft	VIDEO-91540	3.0.1	During a Lync client call to an HDX system, video pixilation or blurriness might result when the Lync client disables and then restarts video.	Use the Pause Video function instead of the End Video function.
Interoperability Microsoft	VIDEO-90594	3.0.2	When the Microsoft Lync client places a call on hold, the HDX system incorrectly indicates that the call was muted.	
Interoperability Microsoft	VIDEO-86180	3.0	Internet Explorer version 8 shares cookies among all active sessions. If you manage multiple HDX systems within the same Internet Explorer 8 browser session, you might encounter unexpected behavior.	When using Internet Explorer 8, do one of the following: Manage only one HDX system at a time. Use the <i>-noframemerging</i> option in each new instance of Internet Explorer for each system.
Interoperability Microsoft	VIDEO-86859	3.0	Calls using the ICE protocol support call rates of up to 1564 kbps.	

Category	Issue ID	Found in Release	Description	Workaround
Interoperability Microsoft	VIDEO-90607	3.0.1	For Microsoft qualification configuration, enable Security Mode in the Admin Settings and select the Medium security profile to ensure secure web (https) access to the HDX system.	
Interoperability Microsoft	VIDEO-98318	3.0.5	In multipoint calls using Lync clients and HDX systems routed via an ICE-enabled RMX system, video artifacts may appear on far-end HDX systems after Hold/Resume is performed.	
Interoperability Microsoft	VIDEO-98341	3.0.5	HDX systems receive very low video frame rates during OCS R2 calls. This causes blurred video on the HDX systems. When this condition occurs, the far-end video on the OCS clients (MOC) is not affected.	
Interoperability Polycom HDX 4500 System	VIDEO-89500	3.0.1	The Polycom ReadManager® SE200 system does not support the HDX 4500 system.	Use Polycom CMA version 5.5 or later.
Interoperability Polycom RMX System	VIDEO-95511	3.0.3	In a call with an RMX system, HDX systems paired with the Polycom Touch Control display an incorrect number of participants.	
Interoperability Polycom RMX System	VIDEO-95449	3.0.3	When HDX systems dial into an RMX system conference, audio might fail during the call.	Upgrade the RMX system to version 7.6.1.
Interoperability Polycom RMX System	VIDEO-88649	3.0	An HDX system cannot dial into a password-protected call on an RMX system using a dial string in the format <code><conference ID>##<password></code> (for example, <code>1111##2222</code>).	Dial into the conference and then provide the password using DTMF tones when prompted.
Interoperability Polycom RMX System	VIDEO-88800	3.0	An HDX system might receive Siren14 audio rather than Siren 22 Stereo audio when it is in a 6 Mbps H.323 call on an RMX system.	Configure the HDX system's preferred call rate as 4096 kbps.

Category	Issue ID	Found in Release	Description	Workaround
Interoperability Polycom RMX System	VIDEO-98319	3.0.5	Content loss may be experienced in a SIP call on an HDX system using RMX conferencing with Avaya System Manager 6.2.0. This scenario can occur when the Avaya system registers two 1XC clients, where one 1XC client uses H.323 signaling and the second 1XC client uses SIP signaling. Content loss happens when the HDX system sends content from People+Content IP. While both 1XC calls initially receive content, content loss may occur when the active speaker changes.	
Interoperability Polycom Touch Control	VIDEO-95369	3.0.4	The Polycom Touch Control cannot perform a Detect Camera function.	Use the web interface to detect newly-installed cameras.
Interoperability Polycom Touch Control	VIDEO-95084	3.0.3.1	On the Polycom Touch Control, the global address book and Favorites pages sometimes appear to be blank.	
Interoperability Polycom Touch Control	VIDEO-91524	3.0.2	Due to synchronization issues between CMA and LDAP, some favorites on the Polycom Touch Control might not be listed.	
Interoperability Polycom Touch Control	VIDEO-88161	3.0	Do not touch or hold the Polycom Touch Control device by the black border outside the visible screen. Doing so may interfere with the Polycom Touch Control device's ability to detect touches.	
Interoperability Polycom Touch Control	VIDEO-88304	3.0	When an HDX system is paired with a Polycom Touch Control device and using a Global Directory Server (GDS), the HDX system downloads directory information only from the server configured in first entry in the directory configuration page.	

Category	Issue ID	Found in Release	Description	Workaround
Interoperability Polycom Touch Control	VIDEO-88331	3.0	If you place a call from the HDX system's web interface and subsequently attempt to dial that site from the Polycom Touch Control device's recent calls list, the call will not connect and will remain in the calling state indefinitely.	Restart the HDX system.
Interoperability Polycom Touch Control	VIDEO-88389	3.0	Do not use an external control panel (such as Crestron or AMX) with an HDX system that is paired with a Polycom Touch Control.	
Interoperability Polycom Touch Control	VIDEO-88850	3.0.0.1	The Polycom Touch Control might display the status of offline HDX systems as Available.	
Interoperability Polycom Touch Control	VIDEO-88862	3.0	When the Polycom Touch Control is paired with an HDX 6000 series system that is configured for a content source but not receiving video on that source, the Polycom Touch Control incorrectly reports that the source is playing.	
Interoperability Polycom Touch Control	VIDEO-93434	3.0.3	If Require Login for System Access is enabled in the HDX system Security Settings, you cannot use Polycom Touch Control to wake up the HDX system after it has gone to sleep.	Use the HDX system web interface to disable the Require Login for System Access setting.
Interoperability Polycom Touch Control	VIDEO-91751	3.0.2	After you disconnect the Polycom Touch Control and press a button on the remote, the HDX system home screen returns after 30 seconds. Also, if you unpair the device through the web interface using the Forget This Device button, the home screen reappears.	

Category	Issue ID	Found in Release	Description	Workaround
Interoperability Polycom Touch Control	VIDEO-91743	3.0.2	When upgrading from a previous software release to the current software release, the Android 2.2 operating system might encounter an open application and the Android 2.2 "Force Close" message is displayed.	Press Enter to close the associated open application and the upgrade process will continue as designed.
Interoperability Polycom Touch Control	VIDEO-89551	3.0.0.2	On occasion when adjusting the volume or brightness slider, the slider does not respond.	Try again.
Interoperability Polycom Touch Control	VIDEO-89553	3.0.0.2	When entering a Meeting Password, asterisks (*) are shown. However, if you navigate away from the screen and back to it, the asterisks are no longer being displayed even though the meeting password has been entered. Also, the information screen shows a green icon indicating that the meeting password has been set.	
Interoperability Polycom Touch Control	VIDEO-97968	3.0.5	When using the Polycom Touch Control and when registered to a Lync server for directory services, the Contacts group is sent to the Polycom Touch Control with a group name of "~" instead of "Contacts."	
Interoperability Polycom Touch Control	VIDEO-98103	3.0.5	When an OTX customer puts a call on Hold from Polycom Touch Control, the primary caller goes on Hold and the remote site remains active	
Interoperability Polycom Touch Control	VIDEO-98159	3.0.5	During H.323 point-to-point calls made at 4M speed, OTX 300 system customers may experience a frozen Venus audio page after increasing the volume to Maximum on a Polycom Touch Control system. When this condition occurs, the Polycom Touch Control system crashes/ freezes and customers cannot lower the volume.	

Category	Issue ID	Found in Release	Description	Workaround
Interoperability Sony	VIDEO-95480	3.0.3.1	At higher call speeds, an HDX system in a call with a Sony PCS-HG90 system shuts down intermittently.	Place calls at lower call speeds, such as 384 kbps.
Interoperability Sony	VIDEO-88119	3.0	HDX systems are unable to send content in H.320 conferences hosted by the Sony PCS-G50 MCU.	
Interoperability SoundStation IP 7000	VIDEO-88170	3.0	When an HDX system is paired with a Polycom SoundStation IP 7000, the HDX system and the SoundStation IP 7000 might occasionally play audio same time.	Do one of the following: <ul style="list-style-type: none"> Lower the volume on one of the two units. Hang up the call and reconnect.
Interoperability TANDBERG	VIDEO-87667	3.0	Encrypted calls between HDX systems and Tandberg systems using 2x56 K ISDN have poor audio and video quality.	
Localization	VIDEO-71092	2.5	Directory entries with localized names longer than 21 characters are truncated on the Edit Entry screen.	Limit localized names to 20 or fewer characters on the Edit Entry screen.
Localization	VIDEO-70798	2.5	Localized system names longer than 13 characters are truncated on some of the system's local interface screens.	Limit localized system names to 13 or fewer characters.
Localization	VIDEO-70797	2.5	Localized meeting names longer than 14 characters are truncated on some of the system's local interface screens.	Limit localized meetings names to 14 or fewer characters.
Localization	VIDEO-70796	2.5	Localized Names in the directory longer than 17 characters are truncated on some of the system's local interface screens.	Limit localized names in the directory to 17 or fewer characters.

Category	Issue ID	Found in Release	Description	Workaround
Localization	VIDEO-80894	2.6	The tilde "~" and minus "-" symbols display as a box on the Calendar and Meeting Details screen when a user is using a Japanese version of Outlook running on the Japanese version of Windows and the HDX system language is configured for Japanese.	
Logging	VIDEO-66818 VIDEO-66119	2.0.5_J	By default, both system and error logs downloaded from an HDX system are named log.txt.	Download the full System Support Package, which contains both system and error logs.
Monitors	VIDEO-51308	1.0	User interface distortion might occur if a monitor is configured with a 4:3 aspect ratio for a resolution of 1280 x 720.	
Monitors	VIDEO-53390	1.0	Distorted video may occur in a multipoint call between PAL and NTSC systems if Zoom People Video to Fit Screen is enabled.	
Monitors	VIDEO-58841	2.0	When Dual Monitor Emulation is enabled, the composite video in multipoint calls with five or more sites is clipped on the left and right sides.	
Monitors	VIDEO-82953	2.6	The only supported display for the HDX 4000 series system is the Polycom display. If a third party display is connected to the HDX 4000 series system, the system will turn off if already powered on, or will not power on if in a powered off state.	.
Monitors	VIDEO-60148	2.0	If Monitor 1 is connected to the HDX system using a different format than what is configured in the user interface, you may get a blank screen.	Press and hold the Display button on the remote control, then select the appropriate format in the remote control window. Or change the monitor format using the web interface.

Category	Issue ID	Found in Release	Description	Workaround
Monitors	VIDEO-77493	2.6	<p>If a VGA monitor is connected to an HDX 9001, 9002, or 9004 system, the HDX system splash screen is tinted green.</p> <p>If a monitor does not support the timing mode selected by U-Boot for its splash screen, the video artifact will depend on the monitor.</p>	Manually configure the HDX system and the monitor to match each other.
Monitors	VIDEO-70791	2.5	Some monitors may fail to correctly center video and user interface screens from an HDX system. If this occurs, use your monitor's horizontal adjustment feature to center the video.	
Monitors	VIDEO-77975	2.5.0.7	If a computer is connected to an HDX system, and the computer's monitor is configured to turn off after a period of inactivity, the monitor will automatically send content when the monitor wakes if Send Content When PC Connects is enabled. Send Content When PC Connects is enabled by default.	To avoid this issue, go to System > Admin Settings > Cameras > Camera Settings and disable Send Content When PC Connects .
Monitors	VIDEO-77717	2.5.0.7	<p>When an HDX system wakes up, Monitor 3 displays distorted video if:</p> <ul style="list-style-type: none"> The VCR/DVD Record Source value for Monitor 3 is Monitor 2. Monitor 2 has the following settings: <ul style="list-style-type: none"> - Video Format: Component YPbPr - Resolution: 1080p - Output Upon Screen Saver Activation: No Signal 	To work around this issue, change the monitor settings or turn Monitor 2 off and then on.
Monitors	VIDEO-84273	2.6.1	If monitor resolution is set to 1920 x 1080, Elapsed time in call information overlaps a part of the Far Site Name when the far site name is in 15 double byte characters or more.	To prevent this problem, limit number of double-byte characters in the near end Site Name to 14 characters.

Category	Issue ID	Found in Release	Description	Workaround
Multipoint	VIDEO-71756	2.5.0.4	A multipoint H.331 broadcast mode call is not supported.	
Multipoint	VIDEO-74435	2.5.0.4	When an HDX system is hosting a multipoint call and is set to Auto Answer Multipoint Video and has a meeting password set, a CMAD or PVX system will not be able to join the call unless it is the first endpoint to connect to the HDX system.	Set Auto Answer Multipoint Video to No on the endpoint that is hosting the call.
Multipoint	VIDEO-75829	2.5.0.5	If a system hosting a multipoint call is configured for a meeting password and the Auto Answer Multipoint Video setting is set to Yes , some meeting password prompts do not display. Specifically, when the second endpoint to call in dials from the web interface, the meeting password prompt is displayed on the second endpoint's local system interface but not on the web interface.	Do one of the following: <ul style="list-style-type: none"> • Before dialing, enter the meeting password in the Meeting Password field on the Place a Call screen in the web interface. • Enter the meeting password using the local system interface.
Multipoint	VIDEO-76240	2.5.0.6	Video from an iPower system is not visible when an HDX system is hosting a multipoint call.	Place a point-to-point call or have each endpoint call into a video bridge.
Multipoint	VIDEO-78352	2.6	When an HDX system uses the Conference on Demand (COD) functionality, a seven-way call is the largest conference that will connect.	Use an RMX system to host the multipoint call if more than seven participants is required.
Multipoint	VIDEO-88455	3.0	Do not use the HDX system's internal multipoint feature with direct connect calls.	
Network	VIDEO-78532	2.5.0.6	When a broadcast storm is created by having two HDX systems connect to a hub and a cable connecting two ports of the hub together, after approximately 10 minutes an HDX system will freeze for several seconds, clear, and then freeze again.	Connect an HDX system to a switch or dedicated LAN port.

Category	Issue ID	Found in Release	Description	Workaround
Network	VIDEO-78531	2.5.0.7	When four HDX systems are connected to a LAN through the same 10M hub, an HDX system restarts if two HDX systems are in a 4M call with the other two HDX systems.	Use a switch or dedicated LAN port instead of a hub.
Network	—	—	When you change the network interface attached to an HDX system from PRI to QBI, make sure to uncheck the box Calling Endpoint Uses the Original ISDN Number before disconnecting the PRI interface. To do this, go to System > Admin Settings > Network > ISDN .	
People+Content™ IP			People+Content IP is unavailable when your security profile is set to Maximum .	
People+Content IP	VIDEO-75903	2.5.0.6	During installation, InstallShield might display an incorrect version number for People+Content IP.	
People+Content	VIDEO-97571	3.0.5	In very rare cases, some HDXs in an RMX conference will not show content received from the RMX. This may occur when content is sent to a participant in conference via Polycom People+Content when SIP signaling is used.	
People on Content™	VIDEO-65397	2.0.3	When using Polycom People on Content on an HDX 4000 series system, do not preview camera 2 before activating People on Content.	
People on Content	VIDEO-90596	2.6.1	When using People on Content with the foreground camera's White Balance set to Auto , the background video may deteriorate over time and blend in with the video of objects in the foreground.	Set the foreground camera's White Balance to Manual before calibrating the camera for use with People on Content or enabling People on Content.

Category	Issue ID	Found in Release	Description	Workaround
Power	VIDEO-80751	2.6	If an HDX system does not have an internal battery and is configured to use a time server, the HDX system will go to sleep shortly after restarting if idle. This is due to the system time being set to the year 1970 until successful connection to the time server. Once the connection to the time server is made, the screen saver wait time is exceeded and the HDX system goes to sleep. This is normal behavior.	
Presence	VIDEO-80195	2.6	When an HDX system is configured to a directory server that supports presence (LDAP, Office Communications Server), presence status is not displayed when a directory search is performed. Presence will be displayed once the directory entry is added to Favorites.	
Profiles	VIDEO-51310	1.0	Profiles do not save Monitor 2 settings.	
Profiles	VIDEO-54970	1.0.2	If the profile you upload to an HDX system includes registration with multiple Global Management System servers, only the first server is registered after the system restarts.	Manually register with the other servers.
Provisioning	VIDEO-80708	2.5.0.7	If an HDX system is configured by the Polycom CMA server to disable Security Mode , the user will be prompted with a log in when attempting to navigate to the HDX system web interface. The log in window will reappear even if the user enters the log in information.	Close the web browser session and navigate to the HDX system's web interface.
Provisioning	VIDEO-80755	2.5.0.5	HDX systems do not successfully register to the CMA provisioning server if the user name contains a dash.	Use a user name that does not contain a dash.

Category	Issue ID	Found in Release	Description	Workaround
Provisioning	VIDEO-80754	2.5.0.5	An HDX system user will not be able to authenticate to the CMA server when going through the setup wizard if the user name is duplicated across multiple domains.	Use a unique user name.
Provisioning	VIDEO-75458	2.5.0.5	If an HDX system is configured for provisioning from the CMA server, you will be unable to log in if Secure Mode in the CMA site provisioning profile is enabled.	Disable Secure Mode in the CMA site provisioning profile. Reconfigure the HDX system with the new profile settings.
Provisioning	VIDEO-80710	2.5.0.6	When the CMA provisions the HDX system with a scheduled provisioned profile that includes the password for a Global Directory (GDS), the HDX system is updated with the password. However, the user interface screen will show that the password has been provisioned, but the web interface will not.	
Provisioning	VIDEO-80707	2.6	The ISDN Gateway check box is not enabled or disabled on the HDX system when the CMA Administrator has pushed a scheduled provisioning profile that includes provisioning values on pages of the CMA scheduled provisioning pages other than the Video Network > IP Network > H.323 Settings page.	Provision the HDX system with values only on the Video Network > IP Network > H.323 Settings page or manually update the HDX system via the local system interface or web interface.
Provisioning	VIDEO-75459	2.5.0.5	If an HDX system is configured for provisioning from the CMA server, you will be unable to log into the system if the following conditions are met: <ul style="list-style-type: none"> Secure Mode in the CMA site provisioning profile is enabled. the DoD DSN Security Profile is configured. 	To work around this issue, delete the system settings by pressing and holding the restore button on the HDX system for 15 seconds while the system powers on. Disable Secure Mode in the CMA site provisioning profile.

Category	Issue ID	Found in Release	Description	Workaround
Provisioning	VIDEO-80706	2.6	The HDX system Gateway Country Code value is not provisioned when the CMA Administrator has created a scheduled provisioning profile with a value for the Gateway Country code.	Update the Gateway Country Code value manually on the HDX system via the local system interface or web interface.
Provisioning	VIDEO-82959	2.6.1	Occasionally, when an HDX system is configured for dynamic management mode with a CMA server, the HDX system is not provisioned with the correct user name based on the provisioned User ID.	
Provisioning	VIDEO-71305	2.5.0.1	HDX systems operating with automatic provisioning check for software updates at an interval specified by the administrator. If an update is required, HDX 4000 series systems perform the update even if they are currently being used as PC displays.	
Provisioning	VIDEO-71440	2.5.0.1	HDX systems sold in Russia do not operate with automatic provisioning.	
Provisioning	VIDEO-76674	2.5.0.6	When an HDX system in dynamic management mode is configured with a static IP address, presence information will not be displayed correctly. To resolve this issue, configure the HDX system for DHCP.	Do not use CMA to dynamically manage an HDX system located behind the VBP-ST Access proxy.

Category	Issue ID	Found in Release	Description	Workaround
Provisioning	VIDEO-81291	2.5.0.5	Occasionally, when an HDX system is being managed by CMA in dynamic management mode, the HDX system will not indicate that the Presence Server is down on the System Status screen when an invalid password is entered on the provisioning page on the web interface (the Provisioning Server will show a red down arrow). Restarting the HDX system results in the Presence Service status displaying the correct status.	
Remote Control	VIDEO-56317	2.0	When the Display button is held down, the HDX system remote control displays some video output formats that are not available for HDX 4000 and 8000 HD series systems.	
Remote Control	VIDEO-82739	2.6	A document will occasionally fail to print when an ISDN call is made and either endpoint performs an action with the remote control. This print failure will occur when two HDX systems have the following settings: <ul style="list-style-type: none"> • PC and printer attached • Serial port mode set to pass through • Baud rate set to 115200 • Flow control to None 	Set the baud rate to 57600.
Sample Sites	—	—	Polycom provides sample numbers in the HDX system directory, as well as video test numbers that you can use to test your HDX system. Please be aware that these numbers may occasionally be unavailable.	
Security	VIDEO-95462	3.0.2.1	After multiple authentication attempts, HDX systems might display performance issues and become unstable.	Select the Enable Session List setting.

Category	Issue ID	Found in Release	Description	Workaround
Security	VIDEO-91358	3.0.2	When External Authentication is enabled, local User credentials do not allow access to the HDX system.	Use local Admin credentials.
Security	VIDEO-51330	1.0	The Security page in both the local and web interface does not correctly report Telnet, SNMP, or Web connections.	
Security	VIDEO-52300	1.0	HDX systems do not issue an SNMP alert for failed or successful attempts to log in via Telnet.	
Security	VIDEO-61292	2.0	When a Meeting Password is set on an HDX 8000 HD series system and multiple sites call it and enter the password in rapid succession, the HDX 8000 HD series system displays blue video.	Press Home , then Near on the remote control.
Security	VIDEO-67094	2.0.5_J	If you attempt to configure an invalid User ID on a system (one that does not meet the system's security policy), you may get an error message that mentions the Admin ID rather than the User ID.	
Security	VIDEO-67093	2.0.5_J	If you attempt to configure an invalid Admin ID on a system (one that does not meet the system's security policy), you may get the error message <i>You must specify an Admin ID</i> rather than one stating that the ID was invalid.	
Security	VIDEO-71560	2.5.0.1	When you change password creation policies, the changes apply to newly created/changed passwords but do not apply to the passwords that existed before the policy change.	
Security	VIDEO-76242	2.5.0.6	In an encrypted point-to-point or multipoint SIP call, the local system interface displays the correct encryption status, but the web interface displays --/9/.	

Category	Issue ID	Found in Release	Description	Workaround
Security	VIDEO-82737	2.6	When the HDX system has Security Mode enabled, you cannot access the system via telnet port 23 or 24. However, the Security Settings screen will still show a green check mark next to Telnet .	
Security	VIDEO-86932	3.0	Because Internet Explorer version 8 shares cookies between all active sessions, you might experience unexpected behavior when managing multiple machines within the same instance of Internet Explorer.	
Security	VIDEO-85889	3.0	If you select the Maximum Security Profile during the setup wizard, any user account information you enter during the setup wizard is not valid after system restart. Active Directory authentication is enabled by default in the Maximum profile, which disables the local user account configured on the HDX system.	
Security	VIDEO-84571	3.0	Polycom's web interface does not enforce session timeouts if you connect using a Chrome browser. Also, if you log out of a web interface session and subsequently navigate back to the web interface, the Chrome browser will "remember" the previous login and will not require you to log in again.	
Security	VIDEO-88401	3.0	When configuring the Maximum Security Profile during the setup wizard, ensure that Require Login for System Access is selected.	
Security	VIDEO-88706	3.0	When configuring the Maximum Security Profile during the setup wizard, ensure that mutual certificate authentication is selected on the Certificates page.	

Category	Issue ID	Found in Release	Description	Workaround
Security	VIDEO-88708	3.0	Immediately after installing a certificate revocation list on the Revocation page of the HDX system's web interface, the restart button on that page has no affect.	Navigate away from the page and then back to it to use the restart button.
Security	VIDEO-88709	3.0	If you have configured the HDX system with a security profile other than maximum and have required that users log in to access the system, non-administrative users will be unable to use the system if they attempt to access a page that requires administrator credentials.	If possible, enter the admin ID and password.
Security	VIDEO-89998	3.0.1	Our current 802.1X implementation on HDX systems supports RFC 2716 only. Other protocols are not supported.	
Security	VIDEO-90405	3.0.1	For security reasons, HDX systems do not support basic or plain text authentication with any SIP server as per RFC 3261.	
Security	VIDEO-97276	3.0.5	Low video frame rate observed in Maximum Security Mode during Point-to-Point calls between two HDX systems (call speed setting @384kbps).	
SNMP	VIDEO-60341	2.0	The Main Camera Up trap is not sent when an HDX system starts up.	
Software Update	VIDEO-51312	1.0	HDX systems do not time out in software update mode if they are waiting for user response.	

Category	Issue ID	Found in Release	Description	Workaround
Software Update	VIDEO-65263	2.0.2	You may observe black video when performing software update on an HDX 9000 series system configured for DVI 1280 x 720 50 Hz. Allow the software update to complete normally. Do not power off the system during the software update process. If the upgrade is interrupted, the system could become unusable.	
Software Update	VIDEO-51950	1.0	When running a software update, you may see video artifacts on secondary monitors. The primary monitor will display the Software Update status screen.	
Software Update	VIDEO-53198	1.0	When updating an HDX system that is behind a Linksys router, the update stalls unless the computer you are using to run the update is configured as host on the network.	
Software Update	VIDEO-60317	2.0	If the Software Update page does not load after a few seconds, click the browser's Refresh button.	
Software Update	VIDEO-60301	2.0	While a software update is in progress, additional browser sessions that attempt to connect to the system may fail to do so, even though the update is proceeding normally.	
Software Update	VIDEO-67352	2.5	HDX 7000 or 8000 series systems customers in a PAL environment will switch to Component monitor output after a Software Update is run with Erase System Flash Memory selected. After the update, hold down the remote control Display button and change the monitor output type.	

Category	Issue ID	Found in Release	Description	Workaround
Software Update	VIDEO-71246	2.5	Downgrading HDX system software from version 2.5 (or later) to 2.0.x (or earlier) erases the system's local directory and CDR file.	To preserve this information, use the system's web interface to download it to your computer before the update.
Software Update	VIDEO-75808	2.5.0.6	If you perform a software update on an HDX system using Microsoft Internet Explorer 8.0, you cannot type in some text fields. Instead, you must use the Browse button. This limitation applies to the following fields: <ul style="list-style-type: none"> • Utilities > Profile Center > Retrieve Settings • Utilities > Import/Export Directory > PC->HDX 7000 HD (Polycom HDX series number will vary based on your system) • Utilities > Screen Saver > Next > Screen Saver Image 	
Software Update	VIDEO-76323	2.5.0.6	If you select a static IP address in the setup wizard, the following message appears: <i>loadXMLDoc: Something is wrong "Access is denied."</i>	To regain access to the software update in the web interface, click OK on the message and then type the new IP address into the Address field of the web browser.
Software Update	VIDEO-88036	3.0	The Software Update feature might occasionally fail to upload an update package successfully.	Refresh the browser page. When the option to select an update package appears, reselect the update package.
Software Update	VIDEO-86401	3.0	Polycom GMS™, Polycom ReadManager SE-200, and Polycom CMA using scheduled provisioning cannot manage HDX systems that have session lists enabled.	Disable session lists on the HDX system's security settings.

Category	Issue ID	Found in Release	Description	Workaround
Software Update	VIDEO-88037	3.0	If you upgrade the HDX system software by using a USB stick while you are logged in to the HDX system through the web interface, you might still see pages from the older version of HDX system software after the upgrade.	Refresh the browser.
Software Update	VIDEO-88883	3.0	HDX system version 3.0 uses a new, more secure method for storing passwords. As a result, you must reconfigure the admin password if you downgrade from version 3.0 or later to a version earlier than 3.0.	
Software Update	VIDEO-88884	3.0	To upgrade to HDX system version 3.0 from version 2.0.3 or earlier, upgrade to version 2.6.1 before upgrading to any later versions.	
Software Update	VIDEO-93526	3.0.3	After a factory reset, upgrading Polycom Touch Control software from version 1.0.x to 1.3.x displays this message: The application <i>PolycomContentService (process polycom.contentService) has stopped unexpectedly. Please try again.</i> The only option is Force Close .	Whether or not you click Force Close , the upgrade completes successfully.
TIP	VIDEO-95616	3.0.4	If TIP is enabled, the HDX system might not successfully call into a TelePresence Server-hosted conference.	When changing the TIP-enabled configuration, disable SIP and then re-enable it. This resets the SIP configuration to apply the TIP setting.
TIP	VIDEO-97680	3.0.5	During Pt-to-Pt calls, Hdx 4500 does not transmit call statistics with the TIP option enabled in Siemens environments. Result is OTX room participants can only see local video.	TIP option should be disabled in Siemens environments.

Category	Issue ID	Found in Release	Description	Workaround
TPS	VIDEO-97915	3.0.5	Periodically, pixelation occurs following movement during TPS conferences in Polycom and CISCO Room Systems. Pixelization resembles a halo that trails behind any moving object.	
TPS	VIDEO-97914	3.0.4	H.323 connections to TPS in the ATT network are not established on single screen HDX systems (HDX 4500). This issue affects only single screen endpoints, during TPS calls. In single screen environments, there is more restrictive size limit of the TCS (cap set) than on other dual screen HDX endpoints.	For AT&T environments, the workaround is to disable Stereo sound.
Transcoding	VIDEO-81287	2.6	If an HDX system hosting a multipoint call has been configured to display content on Monitor 2, content will be displayed on Monitor 1 if a far-end system sends content under the following circumstances: <ul style="list-style-type: none"> • Transcoding is set to OFF. • A multipoint mixed call (IP, ISDN, SIP) is placed. • Downspeeding occurs. 	Enable Transcoding.
Transcoding	VIDEO-98050	-	Transcoding is not supported for HDX 7000 series systems, but an error message does not display when you enter the <i>systemsetting transcodingenabled</i> command.	

Category	Issue ID	Found in Release	Description	Workaround
User Interface	VIDEO-96519 VIDEO-94218 VIDEO-93894 VIDESC-7935	3.0.2	When using remote monitoring or authentication, the HDX system can become sluggish or non-responsive.	Do one of the following: <ul style="list-style-type: none"> In the local interface, go to System > Admin Settings > General Settings > Security > Security Settings. Select Enable Sessions List. In the web interface, go to Admin Settings > General Settings > Security > Security Settings. Select Enable Sessions List.
User Interface	VIDEO-61209	2.0	It may take several minutes for the LAN status indicator to update after the LAN has been reactivated.	
User Interface	VIDEO-61293 VIDEO-65440 VIDEO-63086	2.0.1, 2.0, 2.0.2	The user interface could redraw improperly after repeated changes to the configuration of Monitor 1.	Navigate to another user interface screen, then return to the original screen. If this does not resolve the issue, restart the system.
User Interface	VIDEO-62867	2.0.0_J	When a system is configured for Basic Mode , it does not report far-site information correctly.	
User Interface	VIDEO-81340	2.5.0.5	On the Country screen of the setup wizard, you cannot use the Down arrow key on the remote control to access the Country drop down box.	To work around this issue, use the Up arrow key on the remote control or complete the setup wizard using the web interface.
User Interface	VIDEO-81300	2.5.0.5	If an HDX system is connected to a LAN port with EAP enabled, but EAP is not enabled on the HDX system, the HDX system will report IP network connectivity is up (indicated by a green arrow) when it should show IP connectivity is down (indicated by a red arrow).	Enable EAP/802.1X on the LAN Properties page or move the HDX system to a LAN port that does not have EAP enabled.

Category	Issue ID	Found in Release	Description	Workaround
User Interface	VIDEO-69792	2.5	The statistics for receive content show the maximum that might be received rather than the rate currently being received.	
User Interface	VIDEO-69620	2.5	When you add HDX system microphones one at a time, the Diagnostics screen may list the version of the first microphone as None. If multiple microphones are connected and you restart the system, they are all correctly displayed.	
User Interface	VIDEO-65940	2.0.5_J	Selecting the space bar in the onscreen keyboard toggles between upper-case and lower-case letters.	
User Interface	VIDEO-80600	2.5.0.7	HDX 6000, 7000, and 8000 series systems do not show the IPv6 addresses on the System Information screen when connected to an IPv6 network. This information is displayed in the web interface under Diagnostics > System Information .	
User Interface	VIDEO-80412	2.5.0.5	The HDX system displays an IP address of <i>0.0.0.0</i> on the LAN Properties screen when the LAN cable is disconnected, even if a static IP address was configured on the HDX system.	
User Interface	VIDEO-90228	3.0.1	In a point-to-point call, if the option box Display Icons in a Call is not enabled, pressing Options or Camera on the remote control or the keypad may not work correctly. Pressing the buttons will cause nothing to occur. Display Icons in a Call cannot be enabled while in a call, so the setting must be adjusted before or after calls.	Press Home to return to the main menu and press Options or Camera .

Category	Issue ID	Found in Release	Description	Workaround
Video	VIDEO-91542	3.0.2	During an ISDN point-to-point call, video might sometimes not display on the HDX 9006 system when the HDX system is paired to a Polycom Touch Control.	
Video	VIDEO-90464	3.0.2	The EagleEye Director may indicate variance in the zoom ratio when tracking to a speaker and then re-tracking to the same speaker during the video conferencing session. Depth information used in the zoom algorithm may be unreliable due to the microphone configuration for pan and tilt.	
Video	VIDEO-80580	2.6	Occasionally, when a 6M point-to-point SIP call is made between two HDX systems, the called endpoint displays green video at the bottom of the screen for a couple of seconds when the call initially connects, then displays normal video.	
Video	VIDEO-85838	3.0	Making rapid changes to the selected video source by using API commands might cause the HDX system to display frozen video from one of the sources. To prevent this situation from occurring, allow sufficient time between API commands.	Restart the HDX system.
Video	VIDEO-87018	3.0	You might occasionally notice brief video artifacts when cycling through layouts when using dual monitor emulation. The system will automatically correct these within a couple of seconds.	
Video	VIDEO-85839	3.0	If you use a computer as a People video source, the video on your HDX system might be slightly clipped.	

Category	Issue ID	Found in Release	Description	Workaround
Video	VIDEO-97909	3.0.3	During HDX 9004 system calls, loop back video of RSS4000 recordings (8.0.0.0 rev 19040) become frozen at 128Kbps when VRR setting is Enabled "Live Streaming" and "LPR" setting is Disabled "H.264-HP". This issue only occurs on HDX 9004 systems and only at 128Kbps.	
Web Interface	VIDEO-95484	3.0.1	In the web interface, the Japanese language group names in the directory appear garbled.	
Web Interface	VIDEO-80675	2.6	An HDX system with a BRI card installed and configured for NI-1/NI-2 Switch Protocol does not have the Auto BRI Configuration option in the web interface. The local system interface does have the Auto BRI Configuration option.	
Web Interface	VIDEO-80674	2.6	When an HDX system is configured to automatically answer point-to-point video calls, the web interface does not display a message for an incoming POTS or ISDN voice call for the user to answer the call. The message asking you to accept the call is displayed on the local system interface.	Set Auto Answer Video calls to No . The pop-up message will then be displayed on the web interface.
Web Interface	VIDEO-80605	2.6	In the web interface, Ctrl+Z does not delete text entered into a text field.	Use the Delete key to delete text from a text field.
Web Interface	VIDEO-80603	2.5.0.4	Searching the Directory via the web interface takes up to 45 seconds to retrieve entries if Directory searches are happening on more than 4 simultaneous web interface sessions.	Ensure that only one user at a time performs a directory search.
Web Interface	VIDEO-80106	2.6	HDX systems generate an SNMP alert for each web interface request.	

Category	Issue ID	Found in Release	Description	Workaround
Web Interface	VIDEO-80092	2.6	Occasionally, when configuring the Calendaring Service from the web interface, the green registration check mark is not displayed after selecting the Update page.	Refresh the browser page or configure the Calendaring Service from the local system interface.
Web Interface	VIDEO-80074	2.5.0.5	HDX systems with a V.35 card installed do not issue an SNMP alert when H.320 is enabled or disabled via the web interface.	
Web Interface	VIDEO-80073	2.5.0.5	HDX systems with a PRI card installed do not issue an SNMP alert when H.320 is enabled or disabled via the web interface.	
Web Interface	VIDEO-79759	2.6	Directory group names do not display correctly in the web interface when using Internet Explorer 7 with either Simplified Chinese, Traditional Chinese, or Korean languages.	Use Internet Explorer 6 or Internet Explorer 8.
Web Interface	VIDEO-77721	2.5.0.6	After performing a system reset on an HDX 9004 or 6000 system, the Wake System button on the Camera Settings web interface page might be missing when the system goes to sleep for the first time. The Wake System button is displayed on the web interface after the system is awakened by the remote control.	

Category	Issue ID	Found in Release	Description	Workaround
Web Interface	VIDEO-96330	3.0.3	When a Polycom Classic Viewstation (not EX/FX) joins an existing RMX conference with the HDX system and/or VSX and/or Viewstation EX/FX endpoints, the far site name switches to the name of the Classic Viewstation. However, this does not affect the names displayed onscreen during voice switching. The Classic Viewstation name is only observed under the call statistics screen of the embedded and web interface under Far Site Name. When this error is observed, the Mute Icon of the Classic Viewstation is also displayed on other sites.	Have the Classic Viewstation join the conference first.

This document does not include known issues for HDX systems deployed in Avaya or Broadsoft environments. For information about the known issues in those environments, refer to the Polycom deployment guides for those solutions.

Hardware and Software Requirements

To use the web interface, you need Microsoft Internet Explorer 6.x, 7.x., or 8.x.

To integrate a Polycom SoundStation IP 7000 conference phone with a Polycom HDX system, use the following software versions:

SoundStation IP 7000 Phone Software Version	Polycom HDX Series System Software Version
3.2.1 or 3.2.2 and BootROM 4.2.0	2.5.0.7, 2.5.0.8
3.2.3 and BootROM 4.2.2	2.6.0, 2.6.0.2, 2.6.1, 2.6.1.3
3.3.1 and BootROM 4.3.1	2.6.1.3, 3.0, 3.0.0.1, 3.0.0.2, 3.0.1, 3.0.2, 3.0.2.1, 3.0.3, 3.0.3.1
4.0.1 and BootROM 5.0.1	3.0.3, 3.0.3.1
4.0.2 and Update 5.0.1.10545	3.0.4
4.0.2 and Update 5.0.1.10553	3.0.5

Interoperability



For more information about using Polycom HDX systems as part of a Polycom–partner product solution, refer to the Polycom–partner product deployment guides available at support.polycom.com.

Video conferencing systems use a variety of algorithms to compress audio and video. In a call between two systems, each end transmits audio and video using algorithms supported by the other end. In some cases, a system may transmit a different algorithm than it receives. This process occurs because each system independently selects the optimum algorithms for a particular call, and different products may make different selections. This process should not affect the quality of the call.

Products Tested in this Release

Polycom HDX systems are tested extensively with a wide range of products. The following list is not a complete inventory of compatible equipment. It simply indicates the products that have been tested for compatibility with this release.

Polycom strives to support any system that is standards-compliant and investigates reports of Polycom systems that are not interoperable with other vendor systems.



You are encouraged to upgrade all your Polycom systems with the latest software before contacting Polycom support to ensure the issue has not already been addressed by vendor software updates. Go to PolycomService/support/us/support/service_policies.html to find the current **Polycom Supported Products** matrix.

Product	Interoperable Versions	Tested Versions
NAT/Firewall/Border Controller		
Linksys WRT54G2	1.5.00	
NETGEAR FR114P	1.5 Release 14	
NETGEAR WGR614v10	1.0.2.26_51.0.59NA	
Polycom Video Border Proxy™ (VBP®) 5300-E/S, 4350, 6400-S	11.2.3	
Management Systems and Recorders		
Avaya ACM	R015x.02.1.016.4	
Cisco Unified Communications Manager	6.0, 7.0 (must use Polycom HDX system software version 2.5.0.6_00_cisco-3966)	
Cisco 3745	12.4	
Codian MCU 4505	4.2 (1.43)	
OpenSER	1.0.2	
Polycom Converged Management Application (CMA®) 4000, CMA 5000	5.5.0, 6.0.1	6.0.1
Polycom Distributed Media Application™ (DMA™) 7000	2.3, 3.0, 4.0, 5.0	4.0, 5.0
Polycom Global Management System™ (GMS™)	7.1.10.1	7.1.10
Polycom MGC™	9.0.4.3	
Polycom PathNavigator™	7.0.14	
Polycom ReadManager® SE200	3.0.7 ER1	
Polycom RealPresence® Resource Manager	7.0	7.0
Polycom RMX® 1000	2.1.2-25338	
Polycom RMX 2000™, Polycom RMX 4000	7.2, 7.6	

Product	Interoperable Versions	Tested Versions
Polycom RMX 1500	7.2, 7.6	
Polycom RSS™ 4000	6.4.0, 7.0, 8.0	7.0, 8.0
Polycom Video Media Center™ (VMC™) 1000	2.0 build 5.3.0.110	
RADVISION ECS Gatekeeper	7.1.2.12	
Gatekeeper, Gateways, External MCU, Bridges, Call Managers		
Cisco TelePresence Video Communication Server (VCS)	x7.0.2, X7.1	x7.1
Codian MCU 4505	4.2 (1.50), 4.3(1.68)	4.3(1.68)
Cisco Telepresence ISDN GW 3241	2.1 (1.43)p	2.1 (1.43)p
Cisco 3734 Gatekeeper	12.4	12.4
Cisco TelePresence Multipoint Switch (CTMS)	1.7.2	1.7.2
Cisco TelePresence Server (TPS)	2.2	2.2
Cisco TelePresence Server MSE 8710	2.2	2.2
Cisco United Communications Manager	8.5.1	8.5.1
Polycom CMA	6.0, 6.0.1	6.0.1
Polycom DMA	5.0	
Polycom MGC	9.0.4.3	9.0.4.3
Polycom MGC Gateway	9.0.4.3	9.0.4.3
Polycom RMX	7.6.1, 7.7	7.6.1, 7.7
Polycom RMX 1000	2.1.2	2.1.2
Polycom RMX Gateway	7.6.1, 7.7	7.6.1, 7.7
Polycom ReadManager SE200	3.00.07	3.00.07
Polycom PathNavigator	7.0.14	7.0.14
Radvision Scopia 100 P10 Gateway	5.7.2.0.25	5.7.2.0.25
Radvision ECS Gatekeeper	7.1.2.12	7.1.2.12
TANDBERG Gateway	G3.2	
TANDBERG Gatekeeper	N6.1, N6.3	N6.3
Endpoints		
Aethra Vega X3	12.1.19	12.1.19
Aethra Vega X7	12.1.7	12.1.7
Cisco E20	TE4.0.0.246968, 4.1.1	4.1.1

Product	Interoperable Versions	Tested Versions
Cisco C90	TC4.1.1, TC4.2, 5.0.1	5.0.1
Cisco C20	TC4.1.1, TC4.2, 5.0.1	5.0.1
Cisco EX90	TC4.1.1, TC4.2, 5.0.1	5.0.1
Cisco TelePresence System (CTS)	1.7.2, 1.8.1	1.7.2
DST Broad 5	V2.0	V2.0
DST K60	2.0.1	2.0.1
LifeSize Express	4.7.17(1)	
LifeSize Express 220	4.8.0(59)	
LifeSize Room	4.7.17(1)	
LifeSize Room 200	4.7.17(1), 4.7.19(3), 4.7.20(14)	4.7.20(14)
LifeSize Team	4.1.1(17)	
LifeSize Team 220	4.8.0(59), 4.9.0(73), 4.10.1(7)	4.10.1(7)
LifeSize Desktop Client	2.0.2.191	2.0.2
LifeSize Passport	4.9.2(7)	4.9.2(7)
Polycom CMA Desktop (CMAD)	5.1, 5.2, 5.2.2	5.2.2
Polycom CMAD MAC	5.1, 5.2	
Polycom DSTMedia Broad5	2.0.0	
Polycom DSTMedia K60	2.0.1	
Polycom HDX®	3.0.4, 3.0.5	3.0.4, 3.0.5
Polycom iPower™ 9000	6.2.0.1208	6.2.1208
Polycom PVX	8.0.4, 8.0.16	
Polycom QDX® 6000	4.0.1.1, 4.0.2	4.0.2
Polycom RealPresence Mobile for Android™	1.1	1.1
Polycom RealPresence Mobile for Apple® iPad®	1.2	1.2
Polycom SoundPoint® IP 601	3.1.7.0134, 4.0.2	4.0.2
Polycom SoundPoint IP 650	3.3.1.0769, 4.0.2	4.0.2
Polycom SoundStation IP 4000	3.1.7.0134	3.1.7
Polycom SoundStation IP 7000	4.0.2	4.0.2
Polycom Telepresence m100	1.0	1.0
Polycom Touch Control	1.4, 1.5	1.5

Product	Interoperable Versions	Tested Versions
Polycom V500™, Polycom V700™	9.0.6.1	
Polycom ViewStation® 512	7.5.4	7.5.4
Polycom ViewStation FX	6.0.5	6.0.5
Polycom VSX® 3000, VSX 5000, VSX 6000, VSX 7000, VSX 7000e, VSX 8000	9.0.6.1, 9.0.6.2	9.0.6.2
Polycom VVX® 1500	3.3.1, 4.0.0, 4.0.1, 4.0.2	4.0.2
Radvision Scopia XT1000	2.5.24, 2.5.208, 2.5.308	2.5.308
Sony PCS-1	3.42	3.42
Sony PCS-G50	2.72	2.72
Sony PCS-G70	2.63	
Sony PCS-G90	2.22	2.22
Sony PCS-TL50	2.42	2.42
Sony PCS-XG80	2.30, 2.34	2.34
TANDBERG Edge95 MXP	F9.1, 9.1.1, 9.1.2	9.1.2
TANDBERG 150 MXP	L6.1	L6.1
TANDBERG 880 MXP	F9.1	
TANDBERG 1500 MXP	F9.1	
TANDBERG 1700 MXP	F9.1, 9.1.2	9.1.2
TANDBERG 6000 MXP	F9.1, 9.1.1, 9.1.2	9.1.2
TANDBERG 6000 B Series	B10.3	B10.3
TANDBERG 6000 E Series	E5.3	E5.3
Microsoft Office Communications Server and Microsoft Lync™ Server 2010 Solution		
Microsoft Office Communications Server 2007 R2	2007 SP2	
Microsoft Office Communicator 2007 R2 Client	3.5.6907.244	
F5 BIG-IP Load Balancer 1500	9.1.2 (40.2)	
Microsoft Exchange 2010 server	Update 3	
Microsoft Exchange 2007 server	Update 4 SP2	
Microsoft Outlook 2007	2007 SP2	
Microsoft Outlook 2010	14.0.6112.5000	
Lync2010 SP0	4.0.7457.0	
Lync2010 Client	4.0.7577.4087	

Product	Interoperable Versions	Tested Versions
Lync Attendee	4.0.7577.254	
Lync Attendant Console	4.0.7577.253	
Exchange 2010 SP0	14.00.0702.000	
Polycom Calendar for Microsoft Outlook (PCO)	1.0.7.0 Build 2	
BroadSoft Solution		
BroadSoft BroadWorks	16 SP1	

Camera Compatibility

The following Pan Tilt Zoom (PTZ) cameras are supported for use with Polycom HDX systems:

- Polycom EagleEye View (requires HDX system software 2.6 or later)
- Polycom EagleEye HD
- Polycom EagleEye 1080 (requires HDX system software 2.5 or later)
- Polycom EagleEye II (requires HDX system software 2.6.1 or later)
- Polycom EagleEye III (requires HDX system software 3.0.1 or later)
- Polycom EagleEye Director (requires HDX system software 3.0.1 or later)
- Polycom PowerCam™ Plus (SD camera)
- Polycom PowerCam (SD camera)
- Sony EVI-D30/31 (SD camera)
- Sony EVI-D70 / Vaddio WallVIEW 70 (SD camera)
- Sony EVI-D100 / Vaddio WallVIEW 100 (SD camera)
- Sony BRC-300 / Vaddio WallVIEW 300 (SD camera)
- Elmo PTC-100S/110R/150S/160R (SD camera)
- Canon VC-C50i/Vaddio WallVIEW 50i (SD camera)
- Sony BRC-H700
- Sony EVI-HD1

License Information

OpenSSL License

Copyright (c) 1998-2012 The OpenSSL Project. All rights reserved.

Redistribution and use in source and binary forms, with or without modification, are permitted provided that the following conditions are met:

1. Redistributions of source code must retain the above copyright notice, this list of conditions and the following disclaimer.
2. Redistributions in binary form must reproduce the above copyright notice, this list of conditions and the following disclaimer in the documentation and/or other materials provided with the distribution.
3. All advertising materials mentioning features or use of this software must display the following acknowledgment:

"This product includes software developed by the OpenSSL Project for use in the OpenSSL Toolkit. (<http://www.openssl.org>)

4. The names "OpenSSL Toolkit" and "OpenSSL Project" must not be used to endorse or promote products derived from this software without prior written permission. For written permission, please contact openssl-core@openssl.org.

5. Products derived from this software may not be called "OpenSSL" nor may "OpenSSL" appear in their names without prior written permission of the OpenSSL Project

6. Redistributions of any form whatsoever must retain the following acknowledgment:

"This product includes software developed by the OpenSSL Project for use in the OpenSSL Toolkit (<http://www.openssl.org>)

IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE DISCLAIMED. IN NO EVENT SHALL THE OpenSSL PROJECT OR ITS CONTRIBUTORS BE LIABLE FOR ANY DIRECT, INDIRECT, INCIDENTAL, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES (INCLUDING, BUT NOT LIMITED TO, PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY OUT OF THE USE OF THIS SOFTWARE, EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.

This product includes cryptographic software written by Eric Young (eay@cryptsoft.com). This product includes software written by Tim Hudson (tjh@cryptsoft.com).

Original SSLeay License

Copyright (C) 1995-1998 Eric Young (eay@cryptsoft.com) All rights reserved.

This package is an SSL implementation written by Eric Young (eay@cryptsoft.com)

This library is free for commercial and non-commercial use as long as the following conditions are to. The following conditions apply to all code found in this distribution, be it the RC4, RSA, lhash, DES, etc., code; not just the SSL code. The SSL documentation included with this distribution is covered by the same copyright terms except that the holder is Tim Hudson (tjh@cryptsoft.com).

If this package is used in a product, Eric Young should be given attribution as the author of the parts of the library used. This can be in the form of a textual message at program startup or in documentation (online or textual) provided with the package.

1. Redistributions of source code must retain the copyright notice, this list of conditions and the following disclaimer.
2. Redistributions in binary form must reproduce the above copyright notice, this list of conditions and the following disclaimer in the documentation and/or other materials provided with the distribution.
3. All advertising materials mentioning features or use of this software must display the following acknowledgement:

The word 'cryptographic' can be left out if the from the library being used are not cryptographic related :-).

4. If you include any Windows specific code (or a derivative thereof) from the apps directory (application code) you must include an acknowledgement:

"This product includes software written by Tim Hudson (tjh@cryptsoft.com)

THIS SOFTWARE IS PROVIDED BY ERIC YOUNG ``AS IS" AND ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE DISCLAIMED. IN NO EVENT SHALL THE AUTHOR OR CONTRIBUTORS BE LIABLE FOR ANY DIRECT, INDIRECT, INCIDENTAL, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES (INCLUDING, BUT NOT LIMITED TO, PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY OUT OF THE USE OF THIS SOFTWARE, EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.

The and distribution terms for any publically available version or derivative of this code cannot be changed. i.e. this code cannot simply be copied and put under another distribution [including the GNU Public .]

Copyright Information

© 2013 Polycom, Inc. All rights reserved.

Polycom, Inc.
6001 America Center Drive
San Jose, CA 95002
USA

No part of this document may be reproduced or transmitted in any form or by any means, electronic or mechanical, for any purpose, without the express written permission of Polycom, Inc. Under the law, reproducing includes translating into another language or format.

As between the parties, Polycom, Inc., retains title to and ownership of all proprietary rights with respect to the software contained within its products. The software is protected by United States copyright laws and international treaty provision. Therefore, you must treat the software like any other copyrighted material (e.g., a book or sound recording).

Every effort has been made to ensure that the information in this manual is accurate. Polycom, Inc., is not responsible for printing or clerical errors. Information in this document is subject to change without notice.

Trademark Information

Polycom®, the Polycom “Triangles” logo, and the names and marks associated with Polycom’s products are trademarks and/or service marks of Polycom, Inc., and are registered and/or common-law marks in the United States and various other countries.

All other trademarks are the property of their respective owners.

Patent Information

The accompanying products may be protected by one or more U.S. and foreign patents and/or pending patent applications held by Polycom, Inc.