



*Release Notes*  
*BootROM Application*  
SoundPoint® IP and SoundStation® IP

**Version 4.3.1**  
7 September 2011

Part Number 3804-11069-431

**Trademark Information**

© 2011, Polycom, Inc. All rights reserved. POLYCOM®, the Polycom "Triangles" logo and the names and marks associated with Polycom's products are trademarks and/or service marks of Polycom, Inc. and are registered and/or common law marks in the United States and various other countries. All other trademarks are property of their respective owners. No portion hereof may be reproduced or transmitted in any form or by any means, for any purpose other than the recipient's personal use, without the express written permission of Polycom.

## Table of Contents

1	General.....	7
1.1	Software Revision.....	7
1.2	Important Notes .....	7
1.3	Document Revision .....	8
1.4	Hardware Support.....	8
1.5	Image Signatures .....	8
1.6	Distribution Files .....	9
1.7	BootROM Upgrade/Downgrade Path.....	10
2	Changes by Release .....	11
2.1	Version 4.3.1.....	11
2.1.1	Added or Changed .....	11
2.1.2	Removed Features .....	11
2.1.3	Corrections.....	11
2.2	Version 4.3.0.....	12
2.2.1	Added or Changed Features.....	12
2.2.2	Removed Features .....	12
2.2.3	Corrections.....	12
2.3	Version 4.2.2.....	13
2.3.1	Added or Changed Features.....	13
2.3.2	Removed Features .....	13
2.3.3	Corrections.....	13
2.4	Version 4.2.1.....	14
2.4.1	Added or Changed Features.....	14
2.4.2	Removed Features .....	14
2.4.3	Corrections.....	14
2.5	Version 4.2.0 B.....	15
2.5.1	Added or Changed Features.....	15
2.5.2	Removed Features .....	15
2.5.3	Corrections.....	15
2.6	Version 4.2.0.....	15
2.6.1	Added or Changed Features.....	15
2.6.2	Removed Features .....	15
2.6.3	Corrections.....	15
2.7	Version 4.1.3.....	16
2.7.1	Added or Changed Features.....	16
2.7.2	Removed Features .....	16
2.7.3	Corrections.....	16
2.8	Version 4.1.2 B.....	17
2.8.1	Added or Changed Features.....	17
2.8.2	Removed Features .....	17
2.8.3	Corrections.....	17
2.9	Version 4.1.2.....	17
2.9.1	Added or Changed Features.....	17
2.9.2	Removed Features .....	17

## Release Notes - BootROM 4.3.1

2.9.3	Corrections.....	17
2.10	Version 4.1.1.....	18
2.10.1	Added or Changed Features.....	18
2.10.2	Removed Features.....	18
2.10.3	Corrections.....	18
2.11	Version 4.1.0.....	18
2.11.1	Added or Changed Features.....	18
2.11.2	Removed Features.....	19
2.11.3	Corrections.....	19
2.12	Version 4.0.1 (Limited Release).....	19
2.12.1	Added or Changed Features.....	19
2.12.2	Removed Features.....	19
2.12.3	Corrections.....	19
2.13	Version 4.0.0.....	19
2.13.1	Added or Changed Features.....	19
2.13.2	Removed Features.....	20
2.13.3	Corrections.....	20
2.14	Version 3.2.3RevB.....	20
2.14.1	Added or Changed Features.....	20
2.14.2	Removed Features.....	21
2.14.3	Corrections.....	21
2.15	Version 3.2.3.....	21
2.15.1	Added or Changed Features.....	21
2.15.2	Removed Features.....	21
2.15.3	Corrections.....	21
2.16	Version 3.2.2RevB.....	21
2.16.1	Added or Changed Features.....	21
2.16.2	Removed Features.....	21
2.16.3	Corrections.....	21
2.17	Version 3.2.2.....	21
2.17.1	Added or Changed Features.....	21
2.17.2	Removed Features.....	22
2.17.3	Corrections.....	22
2.18	Version 3.2.1.....	22
2.18.1	Added or Changed Features.....	22
2.18.2	Removed Features.....	22
2.18.3	Corrections.....	22
2.19	Version 3.2.0 (Beta Only).....	22
2.19.1	Added or Changed Features.....	22
2.19.2	Removed Features.....	22
2.19.3	Corrections.....	23
2.20	Version 3.1.3 RevD.....	23
2.20.1	Added or Changed Features.....	23
2.20.2	Removed Features.....	23
2.20.3	Corrections.....	23
2.21	Version 3.1.3 RevC.....	23

## Release Notes - BootROM 4.3.1

2.21.1	Added or Changed Features.....	23
2.21.2	Removed Features.....	23
2.21.3	Corrections.....	23
2.22	Version 3.1.3 RevB.....	23
2.22.1	Added or Changed Features.....	23
2.22.2	Removed Features.....	23
2.22.3	Corrections.....	24
2.23	Version 3.1.3.....	24
2.23.1	Added or Changed Features.....	24
2.23.2	Removed Features.....	24
2.23.3	Corrections.....	24
2.24	Version 3.1.2.....	24
2.24.1	Added or Changed Features.....	24
2.24.2	Removed Features - None.....	24
2.24.3	Corrections - None.....	24
2.25	Version 3.1.1.....	24
2.25.1	Added or Changed Features.....	24
2.25.2	Removed Features - None.....	25
2.25.3	Corrections.....	25
2.26	Version 3.1.0.....	25
2.26.1	Added or Changed Features.....	25
2.26.2	Removed Features - None.....	25
2.26.3	Corrections.....	25
2.27	Version 3.0.1.....	25
2.27.1	Added or Changed Features.....	25
2.27.2	Removed Features - None.....	25
2.27.3	Corrections.....	25
2.28	Version 3.0.0.....	25
2.28.1	Added or Changed Features.....	25
2.28.2	Removed Features.....	26
2.28.3	Corrections.....	26
2.29	Version 2.6.2.....	26
2.29.1	Added or Changed Features - None.....	26
2.29.2	Removed Features - None.....	26
2.29.3	Corrections.....	26
2.30	Version 2.6.1.....	26
2.30.1	Added or Changed Features - None.....	26
2.30.2	Removed Features - None.....	26
2.30.3	Corrections.....	26
2.31	Version 2.6.0.....	26
2.31.1	Added or Changed Features.....	26
2.31.2	Removed Features - None.....	27
2.31.3	Corrections.....	27
2.32	Version 2.5.1.....	27
2.32.1	Added or Changed Features - None.....	27
2.32.2	Removed Features - None.....	27

## Release Notes - BootROM 4.3.1

2.32.3	Corrections - None.....	27
2.33	Version 2.5.0.....	27
2.33.1	Added or Changed Features.....	27
2.33.2	Removed Features - None.....	27
2.33.3	Corrections.....	27
3	Notes.....	27
3.1	Outstanding Issues.....	27

## 1 General

### 1.1 *Software Revision*

These release notes cover Polycom's SoundPoint/SoundStation IP - BootROM version 4.3.1.

### 1.2 *Important Notes*

- The BootROM for the VVX 1500 is not included in this release. For SIP 3.2.2 and future releases, the BootROM (for the VVX product) will be distributed as part of the SIP software image as there is a tight dependency between them. Products other than the VVX 1500 will continue to be supported with a separate BootROM image. Refer to technical bulletin TB 53522 for upgrade instructions.
- BootROM 4.3.0 does **not** include support for the SoundPoint IP 430. BootROM 4.2.0 does **not** include support for the following phone models: SoundPoint IP 300, 301, 500, 501, 600, 601 and SoundStation IP 4000. These are termed 'Legacy' phone models. If you have these phones installed in your network the following options can be used if you wish to upgrade the BootROM to 4.2.0
  - Continue to host an older version of the 'split' BootROM for these phones e.g. you could place bootrom file 2345-11300-001-bootrom1.ld from the BootROM Release 4.1.3 on your provisioning server while updating/replacing the files for other phone models. This step can be achieved by unzipping the BootROM 4.2.0 distribution file into the same directory as an earlier BootROM had been placed and replacing the files for the current phone models.
  - If an applicable 'split' image for the Legacy phone models is not found the phone will still boot, but the boot time will be increased due to the time taken for the phone to search the bootrom.ld file for an applicable image.
- This BootROM version is not compatible with the MGCP application and must not be used on phones running MGCP.
- When the BootROM is changed on the phone the Flash File System is re-formatted. To ensure that user settings such as contacts are preserved across the upgrade, a provisioning server must be used for the phone to store back-up copies of the local settings and contact directory information.
- The Zero Touch provisioning (ZTP) feature introduced in the current release 4.3.1 is "UNSUPPORTED" unless the phones are running both BootROM/Updater version 4.3.1 and UC Software version 3.3.2

### 1.3 **Document Revision**

These release notes may be updated during the life of this release as any issues are reported. This document was last updated September 14, 2011.

### 1.4 **Hardware Support**

This release is compatible with the following Polycom products:

- SoundPoint IP 320
- SoundPoint IP 321
- SoundPoint IP 330
- SoundPoint IP 331
- SoundPoint IP 335
- SoundPoint IP 450
- SoundPoint IP 550
- SoundPoint IP 560
- SoundPoint IP 650
- SoundPoint IP 670
- SoundStation IP 5000
- SoundStation IP 6000
- SoundStation IP 7000
- VVX 1500 (BootROM is distributed as part of the SIP 3.2.2 and later releases)

### 1.5 **Image Signatures**

Cryptographic signatures are added to all downloaded image files as a security feature. BootROMs 3.0.0 and later require that an image has a valid signature to prevent malicious code from being used. Since no prior BootROMs have this signature it is not possible to downgrade the BootROM below 3.0.0. Similarly it will not be possible to run older applications. Care should be taken when deciding to upgrade to later BootROMs.



## 1.6 *Distribution Files*

The following files constitute the **4.3.1.0440** distribution of the SoundPoint IP/SoundStation IP/VVX BootROM software. For centrally provisioned systems, copy these files to the boot server in order to upgrade the BootROM software on the phone.

<b>Files</b>	<b>Description</b>
bootrom.ld	Concatenated BootROM application executable.
2345-12200-002.bootrom.ld 2345-12200-005.bootrom.ld	BootROM executables for SoundPoint IP 320
2345-12360-001.bootrom.ld	BootROM executables for SoundPoint IP 321
2345-12200-001.bootrom.ld 2345-12200-004.bootrom.ld	BootROM executables for SoundPoint IP 330
2345-12365-001.bootrom.ld	BootROM executables for SoundPoint IP 331
2345-12375-001.bootrom.ld	BootROM executables for SoundPoint IP 335
2345-12450-001.bootrom.ld	BootROM executable for SoundPoint IP 450
2345-12500-001.bootrom.ld	BootROM executable for SoundPoint IP 550
2345-12560-001.bootrom.ld	BootROM executable for SoundPoint IP 560
2345-12600-001.bootrom.ld	BootROM executable for SoundPoint IP 650
2345-12670-001.bootrom.ld	BootROM executable for SoundPoint IP 670
3111-30900-001.bootrom.ld	BootROM executable for SoundStation IP 5000
3111-15600-001.bootrom.ld	BootROM executable for SoundStation IP 6000
3111-40000-001.bootrom.ld	BootROM executable for SoundStation IP 7000

## 1.7 *BootROM Upgrade/Downgrade Path*

Due to some enhancements that have been added to the BootROM software, it is not always possible to go to certain versions even if the hardware is compatible. The following table lists the upgrade/downgrade paths that are not supported:

<b>From</b>	<b>Upgrade</b>	<b>Downgrade</b>
1.x	2.x, 3.x, 4.x	
2.0.x, 2.1.x	2.5.x, 2.6.x, 3.x, 4.x	1.x
2.2.x	3.x, 4.x	1.x, 2.0.x, 2.1.x
2.3.x, 2.4.x	3.x, 4.x	1.x, 2.0.x, 2.1.x, 2.2.x
2.5.x	3.x, 4.x	1.x, 2.0.x, 2.1.x, 2.2.x
2.6.x		1.x, 2.0.x, 2.1.x, 2.2.x
3.0.x		1.x, 2.x
3.1.0, 3.1.1		1.x, 2.x
3.1.2, 3.1.3, 3.2.x		1.x, 2.x – All platforms All versions below 3.1.2 - SSIP 4000 only
4.x		1.x, 2.x – All platforms All versions below 3.1.2 - SSIP 4000 only

## **2 Changes by Release**

### **2.1 *Version 4.3.1***

#### **2.1.1 Added or Changed**

- **67633: Added support for Zero Touch Provisioning (ZTP) feature.**

#### **2.1.2 Removed Features**

- None

#### **2.1.3 Corrections**

- **59371: "Initial log entry" is not the initial log entry.**
- **60287: The phone displays misleading messages when it is booting and attempting to contact the boot/provisioning server.**
- **61918: The default value is restored for the flash parameter "dhcp.enabled"**
- **64474: Phone application fails to set up the correct DNS and SNTP settings from the DHCP server.**
- **65461: Phone will attempt a DHCP VLAN discovery even after it receives a VLAN ID from CDP or LLDP.**
- **65660: SoundStation IP 6000, IP 7000: Unprotected access to flash memory may lead to corruption of the phone.**
- **66361: SoundStation IP 6000, IP 7000: When the Path MTU Discovery is disabled on the Windows 2003 server, the phone does not become provisioned using FTP.**
- **67431: When the phone runs continuously during the boot up stage, the phone will not be provisioned as a result of memory allocation errors.**

- 68476: **The phone will not be able to boot if it is configured with Option 60, ASCII String and DHCP Server Option 43.**
- 69195: **SoundStation IP 7000: The "CLink Mode" parameter cannot be edited in the BootROM/Updater setup menu.**
- 69563: **SoundStation IP 6000, IP 7000: The phones' application cannot be upgraded using TFTP.**
- 69671: **Phones fail to receive the VLAN ID from the DHCP option 129 in a specific scenario and boot up with the native VLAN.**
- 69934: **The phone displays incorrect progress notification when it is attempting to update the software image.**

## **2.2 Version 4.3.0**

### **2.2.1 Added or Changed Features**

- None

### **2.2.2 Removed Features**

- 56248: **Removed support for the SoundPoint IP 430.**

### **2.2.3 Corrections**

- 54017: **VVX 1500: Erroneous log timestamps during boot-up.**
- 54219: **SoundPoint IP 560, 670: Phones will not establish a network link when they are connected to a switch when both the phone and the switch have their port settings fixed at 100Mb/Full Duplex.**
- 55648: **Socket bind for passive FTP data connection will use another random port.**
- 56333: **Phone will reboot automatically when the lease time expires after disabling and then enabling the DHCP server.**
- 56381: **SoundStation IP 6000, 7000: Phones do not accept a DHCP offer because the packets from the DHCP server do not include the terminating END (0xFF) option.**
- 56401: **The 'Admin' password length in the boot menu and advanced menu are different.**

- 56868: **Published CDP power values (in TB 48152) do not match actual measured consumption. The fix involved updating the software and technical bulletin.**
- 57629: **A corruption to the Flash configuration will reset, but will not use the factory default values.**
- 57863: **Phones do not accept a DHCP INFORM response if a packet does not contain the END option.**
- 59352: **The phone executes an application despite an image signature error.**
- 59470: **SoundPoint IP 5000: "ModelNumber" element in "DeviceInformation" XML block is not consistent with other phones.**
- 59625: **Automatic BootBlock upgrade fails through MAC.cfg file.**

## **2.3 Version 4.2.2**

### **2.3.1 Added or Changed Features**

- **Added support for SoundStation IP 5000 conference phone.**
- 54041: **Format of DHCP option 60 is now a configurable parameter. Added support for DHCP Option 125 as per RFC 3925.**
- 56912: **Added support for parsing DHCP Vendor Specific Information option 43 as per RFC 2132**

### **2.3.2 Removed Features**

- None.

### **2.3.3 Corrections**

- 45780: **SoundPoint IP 320, 321, 325, 330, 331, 335, 430, 450, 550, 560, 650, 670: MIPS coprocessor zero register may be incorrectly set and may change value upon boot up.**
- 47954: **SoundStation IP 7000-HDX Integration: After a hard reboot of an HDX, the IP 7000 continuously reboots itself.**
- 56017: **BootROM 4.2.x contains unnecessary firmware intended for SoundPoint IP 320, 321, 325, 330, 331, 335, 430, 450, 550, 560, 650, 670 phones.**
- 56303: **Updating the bootBlock fails when re-installing the same bootBlock.**
- 56307: **BootROM 4.2.x: If "RAM Loading" is enabled, (APP\_NET\_LOAD\_FILE\_PATH="sip.ld"), then the BootROM will**

**download the sip.ld image. But then it reboots instead of running the SIP Application software.**

- **56488: SoundStation IP 6000, 7000: DHCP client asks for duplicate options of "Router"(3) and "Domain Name"(15).**
- **57235: SoundPoint IP450: Changes in the display palette have created contrast problems in BootROM.**

## **2.4 *Version 4.2.1***

### **2.4.1 Added or Changed Features**

- **52816: VVX 1500. Combine BootROM with SIP software for distribution/upgrade. See Technical Bulletin TB53522 for more information.**
- **54098: Add support for Automatic BootBlock upgrade**

### **2.4.2 Removed Features**

- **Remove support for VVX1500. BootROM is now combined with the SIP software image.**

### **2.4.3 Corrections**

- **23978: Bootrom doesn't star out Admin password when entering the setup screen**
- **47768: SoundPoint IP 450: CDP power usage advertisement is low for peak power conditions.**
- **50531: SoundStation IP7000: Phone does not startup without network connection when using the PIC cable**
- **52277: SoundPoint IP Phones: Bootrom fails DHCP if server config has a blank password**
- **52712: SoundPoint IP 320, 321, 330, 331, 335: "Loading application" message box overlaps the progress bar**
- **52943: LLDP reported power usage in logs indicates inappropriate power consumption.**
- **54033: SoundPoint IP 320, 321, 330, 331, 335: "Downloading new application" message box overlaps the progress bar**
- **55435: LLDP not used when enabled, as well as CDP/static VLAN/DVD enabled for precedence test.**
- **55583: BootROM does not report correct User Agent in the HTTP and DHCP requests. Introduced in BootROM 4.1.3.**

## 2.5 **Version 4.2.0 B**

### 2.5.1 **Added or Changed Features**

- 52925: **Add support for SoundPoint IP335 platform**

### 2.5.2 **Removed Features**

- None.

### 2.5.3 **Corrections**

- None.

## 2.6 **Version 4.2.0**

### 2.6.1 **Added or Changed Features**

- 32753: **Add support for LLDP protocol**
- 45174: **Upgrade zlib to version 1.2.3**
- 45743: **Upgrade curl library to version 7.19.2**
- 52348: **SoundStation IP 7000-HDX Integration: Support integration with HDX 6000/7000 products.**

### 2.6.2 **Removed Features**

- 48772: **Remove support for Legacy phone models: SoundPoint IP 300, 301, 500, 501, 600, 601, SoundStation IP 4000**

### 2.6.3 **Corrections**

- 13786/29344: **HTTP Digest Authentication does not work on IIS.**
- 27048: **Application load progress bar doesn't match actual progress**
- 43646: **It takes too long to load existing image if users mistakenly specify valid non-existing bootserver on different network.**
- 45658: **Platform string in transmitted CDP packets is not consistent across all SoundPoint IP products.**
- 49696: **After a long loss of Network connectivity during "Downloading new application" the phone receives an IP address but it does not reboot and it does not display any error message**
- 49758: **SoundStation IP7000 gets into a bad state and does not recover from temporarily unplugging network connection during an active call.**

- 51631: **Phone not releasing first assigned IP address when VLAN is set via DHCP**

## **2.7 Version 4.1.3**

### **2.7.1 Added or Changed Features**

- 48197: **Add support for SoundPoint IP 321/331 products.**
- 49115: **SoundStation IP 6000, 7000: Support new revision of Ethernet PHYs.**

### **2.7.2 Removed Features**

- 46268: **Remove DHCP timeout from the settings menu. (All phones except SoundPoint IP300 and IP500)**

### **2.7.3 Corrections**

- 42233: **Phone does not attempt Digest Authentication after redirect**
- 45708: **SoundStation IP 6000, IP 7000: When DHCP is disabled, CDP messages do not contain IP Address data.**
- VOIP-45860: **SoundPoint IP 450: Phone is flickering in dark gray solid background when backlight turns to low (IP450)**
- 46008: **VVX 1500: BootROM - About screen displays inaccurate IP address information when configured with static network settings.**
- 46607: **Phone fails to connect to redirected server running on different system/IP address**
- 46939: **Digest Authentication may fail on first file in the CONFIG\_FILES list**
- 46966: **SoundPoint IP 320, 330, 430, 450, 550, 650, 670; SoundStation IP 4000: HTTP Digest Authentication nonce from phone is always equal to "AAAAAAAAAAAAAAAA"**
- 47620: **SoundStation IP 4000 may get stuck at the Polycom logo screen if the reboot is triggered by IP address change**
- 47908: **SoundStation IP 4000 will not boot up when the switch port is set at 10FD and the LAN Port Mode in the phone UI is also set at 10FD.**
- 48280: **When using TFTP or FTP as the provisioning Server Type, phone does not save directory entries to flash when TFTP or FTP server is not available.**
- 48799: **VVX 1500: In booting up, after the "Running sip.Id" prompt the screen goes white. Phone is still running however.**



- 49274: **SoundStation IP 6000, 7000; VVX 1500: CDP shutdown frame is sent with TTL value of 180 seconds.**
- 49335: **SoundStation phones' model name contain "SSIP" string**

## **2.8 *Version 4.1.2 B***

### **2.8.1 Added or Changed Features**

- **Add support for VVX 1500 hardware**

### **2.8.2 Removed Features**

None.

### **2.8.3 Corrections**

None.

## **2.9 *Version 4.1.2***

### **2.9.1 Added or Changed Features**

- 29024: **Add ability to disable PC Ethernet port (full support requires SIP 3.1.0 or later)**
- 40755: **Add support for SoundPoint IP450 product**
- 41721: **Add SoundStation IP7000 video unit integration support**
- 43776: **Add IP560,IP670 Gigabit Ethernet 1000FD Master/Slave clocking configuration (full support requires SIP 3.1.0 or later)**

### **2.9.2 Removed Features**

- 42620: **Remove SAS-VP Provisioning Option from the User Interface**

### **2.9.3 Corrections**

- 37580: **SoundPoint IP601: Multicast rate limiting is not enabled**
- 39642: **SoundStation IP6000, IP7000: Phone should not reply to IP packets of unknown protocol with ICMP messages**
- 40328: **Phone hanging on HTTP PUT with authentication**
- 40400: **Phone issuing DHCP Inform packet un-necessarily.**
- 41366: **Update phone UI and documentation to properly reference 'CDP'**
- 42813: **Phone repeating USER AGENT in HTTP request.**
- 42969: **Malformed DHCP option can cause phone to re-boot.**

## 2.10 *Version 4.1.1*

### 2.10.1 Added or Changed Features

- 35976: Add support for SoundPoint IP670 platform
- 36859: Add support for SoundStation IP 6000 platform
- Add support for SoundStation IP 7000 platform
- 34934, 39547: New 8MB flash device support on SoundPoint IP 550, 560, 650 phones
- 40475: Set VLAN Filtering to 'Off' by default

### 2.10.2 Removed Features

None.

### 2.10.3 Corrections

- 39998: Spelling/grammar error in reporting incompatible sip.Id load.
- 40121: VLAN tag not added to frame that is an IP fragment with between 1 and 3 octets of payload
- 40309: Negative cache is not created when doing an nslookup without using the FQDN
- 41199: 802.1x packets do not get forwarded by SoundPoint IP 320, 330, 430, 550, 560, 650 phones

## 2.11 *Version 4.1.0*

### 2.11.1 Added or Changed Features

- 35150: Add electronic hook-switch capability using Jabra DHSG protocol on SoundPoint IP 320, 330, 430, 550, 560, 650 phones. This feature requires SIP 3.0.0 or later software release to operate. Refer to technical bulletin 35150 for more details.
- 37256: Add Jabra Jx10 electronic hook switch support on SoundPoint IP 320, 330, 430, 550, 560, 650 phones. Requires an "Interface Cable" from the headset base to the phone for use. Refer to technical bulletin 35150 for more details.
- 39072: Reduce DHCPINFORM retry timeouts.
- 39330: Make DHCPINFORM only apply if boot server address is Null or 0.0.0.0.
- 39695: Change minimum syslog.renderLevel to 0 from 1

### 2.11.2 **Removed Features**

None.

### 2.11.3 **Corrections**

- 27607: **Image Copyright info is not up to date.**
- 39584: **Large application software images cannot be loaded. Affects SoundPoint IP 550, 560 and 650 phones. Does not affect SIP 3.0.0 or earlier releases.**

## 2.12 ***Version 4.0.1 (Limited Release)***

### 2.12.1 **Added or Changed Features**

- 35817: **Native VLAN ID, Auxiliary VLAN ID and CDP Power usage are logged.**
- 36483: **Add support for SoundPoint IP 560 platform.**
- 38357: **Add ability to adjust the maximum brightness of the SoundPoint IP 550 and 650 phones.**
- 38654: **Add support for SoundPoint IP 320 Part Number 2345-12200-005 and SoundPoint IP 330 Part Number 2345-12200-004 for China market.**

### 2.12.2 **Removed Features**

None.

### 2.12.3 **Corrections**

- 27621: **FTP Password may disappear in a specific scenario.**
- 32535: **"Running 'sip.Id' " screen on IP430 has unwanted vertical line on the display.**
- 37923: **Phone stuck in reboot loop if app checksum is incorrect.**

## 2.13 ***Version 4.0.0***

### 2.13.1 **Added or Changed Features**

- 25274: **Send Vendor ID information through DHCP.**
- 26623: **Add application version to boot log.**
- 29030: **Add automatic provisioning support for individual image files.**
- 33652: **Add SYSLOG feature.**
- 34401: **Add BootROM update progress bar.**

- 34625: **Add ability to discover provisioning server address using DHCPINFORM.**
- 35316: **Add phone serial (MAC address) to user-agent string of HTTP Get.**
- 35361: **Add ability for parameters in MAC.cfg to be overridden by model or platform specific versions.**
- 35362: **Add part number and substitution macros for parameter values in MAC.cfg.**
- 36030: **Add Ethernet Ingress Filtering for DoS suppression and VLAN filtering.**
- 36228: **Add support for 16 levels of gray on LCD in BootROM on SoundPoint IP 550 and 650 platforms.**

### 2.13.2 **Removed Features**

- 35344: **BootROM will not provision configuration files anymore.**
- 35350: **BootROM will not support start type that triggers a bootROM upgrade.**

### 2.13.3 **Corrections**

- 27145: **DHCP timeout setting is not used.**
- 27981/11858: **DHCPDECLINE not sent if duplicate IP detected by DHCP client on SoundStation IP 4000.**
- 33365: **Boot time is too long with unreachable boot server.**
- 35463: **Phone booting via URL displays password in boot log file.**
- 36107: **SoundStation IP 4000 drops max size packets with VLAN enabled.**
- 36658: **DHCP broadcast flag is set on SoundPoint IP 330/320, 430, 550 and 650 phones.**
- 36659: **DHCP Request does not use same 'xid' as the DHCP Offer.**
- 36682: **DHCP: xid and IP header ID does not change on SoundPoint IP 320, 330, 430, 550, 650, and SoundStation IP 4000.**
- 36905: **CDP packet always advertises LAN duplex mode as "Duplex: Full" on SoundPoint IP 300, 301, 500, and 501.**

## 2.14 **Version 3.2.3RevB**

### 2.14.1 **Added or Changed Features**

- 32146: **Add support for SoundPoint IP 330 product.**

- 33391: **Add support for SoundPoint IP 320 product.**

#### 2.14.2 **Removed Features**

None.

#### 2.14.3 **Corrections**

None.

### 2.15 **Version 3.2.3**

#### 2.15.1 **Added or Changed Features**

- 16110: **Add support for SoundPoint IP 550 platform.**

#### 2.15.2 **Removed Features**

None.

#### 2.15.3 **Corrections**

- 34899: **Phones can lose internal configuration after loss of power.**
- 35063: **SoundPoint IP650 should request 6W (was 5W in prior release) for PoE usage.**
- 35068: **Reduce PoE power level requested by SoundPoint IP601 when configured for Expansion Module use (EM\_Power=1) to 11W (was 12W).**

### 2.16 **Version 3.2.2RevB**

#### 2.16.1 **Added or Changed Features**

- 14874: **Add support for SoundPoint IP 650 platform.**

#### 2.16.2 **Removed Features**

None.

#### 2.16.3 **Corrections**

- 18766: **Ethernet transmit level is low on IP 430 platform.**

### 2.17 **Version 3.2.2**

#### 2.17.1 **Added or Changed Features**

- 17412: **Add ability to set Ethernet link mode on IP430 and IP 4000 platforms.**

## 2.17.2 **Removed Features**

None.

## 2.17.3 **Corrections**

- 17134: **BootROM 'About' screen on IP430 shows incorrect VLAN initially for few seconds and then goes to the correct one.**

## 2.18 **Version 3.2.1**

### 2.18.1 **Added or Changed Features**

- 11678: **Add template support in master config. file.**
- 15930: **Add ability to set Ethernet link mode on IP 601.**

### 2.18.2 **Removed Features**

None.

### 2.18.3 **Corrections**

- 12337: **LCD flickers on IP 430.**
- 15956: **Phone fails to up/download file after an up/download fails during data transfer.**
- 16021: **Ftp downloads may fail because phone improperly times out connect attempts.**
- 16629: **Set transfer time-out for image file download to worst case scenario.**

## 2.19 **Version 3.2.0 (Beta Only)**

### 2.19.1 **Added or Changed Features**

- **Add support for IP4000 PoE PIM.**
- 13552: **Improve boot-up diagnostics.**
- 13813: **Add the ability for file transfers to attempt to contact multiple IP's per DNS name.**
- 14400: **Phone can take up to 30 minutes to boot when HTTP goes through TCP timeouts.**
- 14625: **BootROM takes 15 minutes if DNS server IPs are not valid.**

### 2.19.2 **Removed Features**

None.

### 2.19.3 Corrections

- 14673: @ character is not accepted as part of the FTP user name, password, or filename.
- 14844: Failed downloads of pre-existing files causes deletion of pre-existing files.
- 15614: Having different parameters in flash based on platform can cause issues.

## 2.20 *Version 3.1.3 RevD*

### 2.20.1 Added or Changed Features

None.

### 2.20.2 Removed Features

None.

### 2.20.3 Corrections

- 12337: LCD flickers on IP430.

## 2.21 *Version 3.1.3 RevC*

### 2.21.1 Added or Changed Features

- 12414: Add support for IP 430 hardware platform.

### 2.21.2 Removed Features

None.

### 2.21.3 Corrections

- 15986: BootROM boots from a cached copy after downloading a wrong signature load.

## 2.22 *Version 3.1.3 RevB*

### 2.22.1 Added or Changed Features

- 9873: Maintain Ethernet link during boot-up sequence on IP 4000.

### 2.22.2 Removed Features

None.

### 2.22.3 **Corrections**

None.

## 2.23 **Version 3.1.3**

### 2.23.1 **Added or Changed Features**

- 14052: **Add ability to disable Expansion Module support and reduce CDP power requirements accordingly.**
- 14886: **Change the power reported via CDP to the minimum required value.**

### 2.23.2 **Removed Features**

None.

### 2.23.3 **Corrections**

- 13793: **For HTTP digest authentication, cnonce from our phone is not random.**
- 14489: **Phone won't upload all log files to TFTP boot server if log\_file\_directory specified on MAC.cfg doesn't exist on IP 300, IP 400 and IP 500.**
- 15104: **CDP incorrectly advertises new link duplex levels on IP 4000**

## 2.24 **Version 3.1.2**

### 2.24.1 **Added or Changed Features**

- 13910: **Prevent SSIP 4000 from downgrading to BootROM versions that have bug #13361.**
- 13911: **Auto detect and correct bug #13361 on SSIP 4000.**

### 2.24.2 **Removed Features - None.**

### 2.24.3 **Corrections - None.**

## 2.25 **Version 3.1.1**

### 2.25.1 **Added or Changed Features**

- 13475: **User agent headers for HTTP will include the MAC address of the phone when SAS-VP is enabled.**



**2.25.2 Removed Features - None.**

**2.25.3 Corrections**

- 13361: **SSIP 4000 may lose the custom CA Certificate or the SAS-VP ID after file system activity.**

**2.26 *Version 3.1.0***

**2.26.1 Added or Changed Features**

- 8761: **Added IP 601 support.**

**2.26.2 Removed Features - None.**

**2.26.3 Corrections**

- 11857: **Phone ignores short DHCP packets on SSIP 4000 SIP.**

**2.27 *Version 3.0.1***

**2.27.1 Added or Changed Features**

- 11633: **Use flash credentials when URLs lack them.**

**2.27.2 Removed Features - None.**

**2.27.3 Corrections**

- 2179: **FTP password is present in the boot logs.**
- 11409: **Provisioning may not work reliably with the proftpd FTP server on Linux.**
- 11417: **Phone may not be able to boot from a remote subnet.**

**2.28 *Version 3.0.0***

**2.28.1 Added or Changed Features**

- 7663, 8970, 9299: **Added ability to specify addresses as URLs.**
- 7847: **Added support for HTTP boot server transport for SPIP 301/501/600/601 and SSIP 4000.**
- 7895: **Add support for provisioning signed images only.**
- 9579: **Allow specific master config file to be specified in boot server URL.**

## 2.28.2 **Removed Features**

- 11973: **Removed support for port mode (Active) FTP server configurations**  
Use an FTP server/firewall that supports passive mode connections.

## 2.28.3 **Corrections**

- 9043: **Phone does not reboot after a CDP VLAN change.**

## 2.29 **Version 2.6.2**

### 2.29.1 **Added or Changed Features - None.**

### 2.29.2 **Removed Features - None.**

### 2.29.3 **Corrections**

- 8553: **DHCP short packets are ignored in the BootROM. Not fixed for SoundStation IP 4000 SIP.**
- 11278: **DHCP decline not sent on duplicate IP address. Not fixed for SoundStation IP 4000 SIP.**

## 2.30 **Version 2.6.1**

### 2.30.1 **Added or Changed Features - None.**

### 2.30.2 **Removed Features - None.**

### 2.30.3 **Corrections**

- 9447: **Phone fails to boot if the boot server is not present and the application is not self-provisioning.**
- 9537: **When using TFTP, the phone does not display the “Phone could not contact the boot server” screen.**
- 9581: **Phone does not format the file system if the application does not fit.**

## 2.31 **Version 2.6.0**

### 2.31.1 **Added or Changed Features**

- 5761: **Added support for the SoundStation IP 4000 SIP.**
- 7175: **Made TFTP file provisioning consistent with FTP.**
- 8232: **Added DHCP VLAN Discovery.**
- 8760: **Added support for the SoundPoint IP 301.**

**2.31.2 Removed Features - None.**

**2.31.3 Corrections**

- 6782: Invalid <MAC>.cfg can hang the phone.
- 8548: Phone waits 2.5 minutes for SNTP to fail.

**2.32 *Version 2.5.1***

**2.32.1 Added or Changed Features - None.**

**2.32.2 Removed Features - None.**

**2.32.3 Corrections - None.**

**2.33 *Version 2.5.0***

**2.33.1 Added or Changed Features**

- 5116: Added support for the SoundPoint IP 300.

**2.33.2 Removed Features - None.**

**2.33.3 Corrections**

- 5191: FTP provisioning fails if the FTP server root directory is not readable.
- 5623: Hitting the left arrow key before the cursor advances moves the cursor 2 spaces.
- 5668: Spaces in the admin password are ignored.
- 5754: Phone did not log out of FTP server after a BootROM update.

## **3 Notes**

### **3.1 *Outstanding Issues***

None