

Release Notes

Polycom® Cloud Relay

Patch ID: v.1.1.1-6e6b9d7

Released Files: polycom-cloud-relay-1.1.1-6e6b9d7.ova
polycom-cloud-relay-1.1.1-6e6b9d7.zip

Release Date: May 9, 2018

Part Number 3725-85297-001 Rev B

This release of the Polycom Cloud Relay adds improvements and fixes for relay monitoring.

Resolved Issues and Improvements

Issues	Summary
EN-84744	Changing DNS settings doesn't affect currently running containers like cr-logging.
EN-84397	Cloud Relay – polycom-nimbus.servicebus.windows.net should be added to DNS resolution section of the connectivity check.
EN-84398	Cloud Relay – polycom-nimbus.servicebus.windows.net should be added to DNS resolution section of the connectivity check.
Improvements	
	Aligned cr-logging image with other services
	Include tcpdump in cloud relay image
	Avoid spinning while services remain answerable

Upgrade Notes

Polycom recommends using the latest Polycom Cloud Relay to take advantage of any enhancements that may require a new image. The Polycom Cloud Relay cannot be upgraded, but instead you must replace the image. You must install a new image with a unique IP address and turn off the old image after you have reconfigured the new one.

See the Polycom Cloud Relay Deployment Guide for more details.