

Patch Notes

Polycom® RealPresence® Collaboration Server 8.7.4.1

Build ID: 8.7.4.243
Released File: OVA, ISO, BIN, Upgrade File
Release Date: September 7, 2017

Purpose

This patch includes fixes for the following issues when applied over the RealPresence Collaboration Server 8.7.4 generally available (GA) release.

ID	Description
BRIDGE-27359	RMX intermittently sends no video to Skype for Business client in VMR
BRIDGE-27486	Cisco telepresence secure TIP calls drops in Prefer TIP VMR .
BRIDGE-27307	No video sent by RMX to AVMCU in realconnect call (online)
BRIDGE-27428	RMX 1800 does not boot after soft reboot.
BRIDGE-27381	All participants in a Realconnect call dropped, when about same time one conference was finishing. The conference resumed again automatically one minute later.
BRIDGE-27427	Netra stuck. Unit crashes and no Skype for Business video for Polycom participants.
BRIDGE-27419	Logs are flooded.
BRIDGE-27402	RMX showing garbage participant name in Lync Roster list when H323 EPs dialing in conference with system containing '@' in system name string.
BRIDGE-27401	MIPs and ACK failures are being seen on the RMX.
BRIDGE-27414	Intermittent frozen video experienced by one EP
BRIDGE-27386, BRIDGE-27374	RMX random reboot
BRIDGE-27368	Display site names on the endpoints.
BRIDGE-27335	AMP and VMP logs are not generated in the logger files.
BRIDGE-27334	RMX rebooted itself during live conference. Core dumps created. McmsDaemon reset due to WD policy decision.
BRIDGE-26860	PSTN Skype Participant not shown in VTC part count
BRIDGE-27290	RMX did not fully connect AVMCU and threw exceptions at confparty.
BRIDGE-27262	CTS room can't hear the EQ audio (to put the conference ID) after RMX upgrade. DTMF is accepted and can get into meeting.
BRIDGE-27229	Once the user receives the RMX GW IVR, a busy tone is heard when an incorrect destination number is entered, and there is no IVR offering to retry a new destination.
BRIDGE-27164	Complaints about the inconsistent layout behaviour in the layout in a Speaker Priority configured conference.
BRIDGE-27145	Power offCardsCard ID:2, Card Type:mpm, Description: Power off problem.
BRIDGE-27456	RMX 1800: Realconnect cascade link is failing intermittently
BRIDGE-24925	RealConnect functionality in conjunction with cascade for size: Participants connected to slave RMX conference hear IVR waiting for chairperson.
BRIDGE-26322	RMX intermittently responds with 304 POLYCOM-RMX "Media type not available" to REINVITE.

These patch notes document only the changes from the pre-requisite generally available (GA) release. Please refer to the *Polycom RealPresence Collaboration Server 8.7.4 Release Notes* for the complete documentation of that release.

Prerequisites and Configuration Considerations

Please refer to the *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.

Limitations

Please refer to the *Polycom RealPresence Collaboration Server 8.7.4 Release Notes*

Installation Notes

Please refer to the *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.

Rollback Considerations

Please refer to the *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.