

Patch Notes

Polycom® RealPresence® Collaboration Server

Build ID: 8.7.5.765

Released File: OVA, ISO, BIN, Upgrade File

Release Date: October 31, 2018

Purpose

This patch includes fixes for the following issues when applied over the RealPresence Collaboration Server 8.7.5.1.1 release.

<i>Issue ID</i>	<i>Category</i>	<i>Description</i>
EN-109480	Alert Management	Major voltage active alarm reported and failed to clear after normal restore of Power supply.
EN-108601	Audio	Endpoint received distorted audio during conference hosted on RMX.
EN-106636	Content	Participant was not able to share content in VMR after interrupted content sharing from Cisco endpoint
EN-103619	Video	RMX did not decode inbound video stream from Cisco Spark Room.
EN-101639	General	Added support to show overlay layout at extreme corners to avoid getting active speaker image obscured.
EN-86803	Stability	MPMRX got powered off during ongoing conference.
EN-104124	Stability	Onhoing call disconnected abruptly due to card crash.
EN-102695	General	Logs were not being purged.
EN-104861	Video	RMX was not sending video to AVMCU intermittently.

These patch notes document only the changes from the prerequisite generally available (GA) release. Refer to the Release Notes for that GA release for the complete release documentation.

Prerequisites and Configuration Considerations

For information on prerequisites and configuration, please refer to the *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.

Installation Notes

For information on installation, please refer to the *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.

Rollback Considerations

For information on rollbacks, please refer to the *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.