

## Patch Notes

# Polycom® RealPresence® Collaboration Server

---

**Build ID:** 8.7.5.796

**Released File:** OVA, ISO, BIN, Upgrade File

**Release Date:** February 4, 2019

## Purpose

This patch includes fixes for the following issues when applied over the RealPresence Collaboration Server 8.7.5.3 release.

<i>Issue ID</i>	<i>Category</i>	<i>Description</i>
EN-116889	Stability	Core dump was observed during an ongoing call.
EN-115805	Stability	Call is getting dropped for an endpoint during an ongoing conference.
EN-115683	General	Layout was not correct for RPIS321 in the RealConnect meeting.
EN-115623	General	Correct RDP capabilities were not reflected after RMX reboot.
EN-109168	Stability	MPMRx card powered off due to a dial out connectivity problem.
EN-113878	Stability	Core dump observed, RMX rebooted automatically.

These patch notes document only the changes from the prerequisite generally available (GA) release. Refer to the Release Notes for that GA release for the complete release documentation.

## Prerequisites and Configuration Considerations

For information on prerequisites and configuration, please refer to the *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.

## **Installation Notes**

For information on installation, please refer to the *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.

## **Rollback Considerations**

For information on rollbacks, please refer to the *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.