

Patch Release Notes

Polycom® RealPresence® Collaboration Server

Build ID: 8.8.0.493
Released File: OVA, ISO, BIN, Upgrade File
Release Date: May 24, 2019
Part Number: N/A

Purpose

This patch includes fixes for the following issues when applied over the RealPresence Collaboration Server 8.8.0.2 release.

<i>Issue ID</i>	<i>Category</i>	<i>Description</i>
EN-129672	Video	Video freeze observed for some seconds due to packet loss during ongoing conference.
EN-136080	Video	Shrunked, distorted video observed on HDX4500 during an ongoing conferene call.
EN-136078	General	Inforcollector was not able to collect all the required local tracer files and information after a card crash.
EN-136074	Content	Content sharing to TIP-enabled conferences did not work for H.323 endpoints when connected at line rates below 768K.
EN-134683	Stability	Media card rebooted causing all active calls to drop.
EN-136079	Stability	IpMedia core dump observed with media recovery alarms causing all running conferences to drop.
EN-134680	General	H323 Call Setup event is not recorded in CDR for H.323 calls.
EN-115631	Stability	SoftBlades associated with RMX were getting disconnected at random intervals.
EN-136530	Stability	Siptask core dump occurred causing all active calls to drop.
EN-136075	Call Management	AV/MCU cascade failed if focus URI is more than 119 characters.

These patch notes document only the changes from the prerequisite generally available (GA) release. Refer to the Release Notes for that GA release for the complete release documentation.

Prerequisites and Configuration Considerations

For information on prerequisites and configuration, please refer to the *Polycom RealPresence Collaboration Server v8.8.0 Release Notes* and *Polycom RealPresence Collaboration Server v8.8 Administrator Guide*.

Installation and Upgrade Notes

For information on installation, please refer to the *Polycom RealPresence Collaboration Server v8.8.0 Release Notes*.