



# Patch Notes

## Polycom<sup>®</sup> RealPresence<sup>®</sup> Collaboration Server

---

**Build ID:** 8.8.1.2454  
**Released File:** OVA, ISO, BIN, Upgrade File  
**Release Date:** Nov 18<sup>th</sup>, 2019

### Purpose

This patch includes fixes for the following issues when applied over the RealPresence Collaboration Server 8.8.1 release.

Issue ID	Description
EN-156951	Media card reboot observed due to FPGA (Field Programmable Gate Error) error causing active calls to drop.
EN-156963	New users were not able to connect to a VMR conference in 5x5 layout when the recording link is connected with 20 or more participants.
EN-156957	Users experienced video bleed issue on RMX 2000 during an ongoing conference, video from unknown party flashing intermittently in one cell.
EN-156933	In a RealConnect call, Microsoft Skype for Business client observed frozen video causing all active calls to drop.
EN-156936	RMX 8.8.1 could not be added as a network device instance in the RealPresence Resource Manager.
EN-158323	Fallback build version was incorrect for RPCS1800 in case of upgrade/downgrade from 8.8.1 Release.

These patch notes document only the changes from the prerequisite generally available (GA) release. Refer to the Release Notes for that GA release for the complete release documentation.

### Prerequisites and Configuration Considerations

For information on prerequisites and configuration, please refer to the *Polycom RealPresence Collaboration Server v8.8.1 Release Notes* and *Polycom RealPresence Collaboration Server 8.8.1 Administrator Guide*.

### Installation and Upgrade Notes

For information on installation, please refer to the *Polycom RealPresence Collaboration Server 8.8.1 Release Notes*.