



Patch Release Notes

Polycom[®] RealPresence[®] Collaboration Server

Build ID: 8.8.1.3637
Released File: OVA, ISO, BIN, QCOW2, Upgrade File
Release Date: January 6th, 2021

Purpose

This patch includes fixes for the following issues when applied over the RealPresence Collaboration Server 8.8.1.5 release.

<i>Issue ID</i>	<i>Category</i>	<i>Description</i>
EN-183860	Stability	An RMX system upgrade failed due to disk space availability.
EN-193470	Video	Video from a Cisco endpoint was not visible to other participants in conference due to video decoding issue.
EN-192775	Stability	An RMX system process crash and the system rebooted due to an invalid pointer reference.
EN-191884	Stability	An RMX system became unresponsive due to a video process crash.
EN-192238	Audio	In an active conference, an endpoint was sent black video and noise due to a specific audio decoder issue.
EN-193004	Stability	An RMX system rejected an incoming call because it received a Clariti token although it was not licensed for Clariti.
EN-193229	Audio/Video	WebRTC calls made from an RMX system on an upgraded Chrome version failed to send and receive media with other parties in conference.
EN-188603	Stability	An RMX 4000 system rebooted unexpectedly when analytics was enabled.
EN-188369	Content	In an RMX system meeting room, content from a BlueJeans system was not recorded on the recording server.

These patch notes document only the changes from the prerequisite generally available (GA) release. Refer to the Release Notes for that GA release for the complete release documentation.

Prerequisites and Configuration Considerations

For information on prerequisites and configuration, please refer to the *Polycom RealPresence Collaboration Server v8.8.1 Release Notes* and *Polycom RealPresence Collaboration Server 8.8.1 Administrator Guide*.

Installation and Upgrade Notes

For information on installation, please refer to the *Polycom RealPresence Collaboration Server 8.8.1/8.8.1.4 Release Notes*.