



Patch Notes

Polycom[®] RealPresence[®] Collaboration Server

Build ID: 8.9.0.3135
Released File: OVA, ISO, BIN, QCOW2, Upgrade File
Release Date: August 10th, 2020

Purpose

This patch includes fixes for the following issues when applied over the RealPresence Collaboration Server 8.9.0.2 release.

<i>Issue ID</i>	<i>Category</i>	<i>Description</i>
EN-181853	Video	After a few minutes in conference, video of endpoints registered to the Cisco Expressway server were not visible to other endpoints.
EN-180658	General	Disabling TLS v1.1 was not possible on the RMX Signaling interface.
EN-179980	General	The RMX Manager shows English language no matter which language is configured in its Multilingual Setting tab.
EN-175990	Content	The Poly RealPresence Desktop was not able to receive content after content was re-started by sender due to incorrect content rate calculation at the RMX.

These patch notes document only the changes from the prerequisite generally available (GA) release. Refer to the Release Notes for that GA release for the complete release documentation.

Prerequisites and Configuration Considerations

For information on prerequisites and configuration, please refer to the *Polycom RealPresence Collaboration Server v8.9.0 Release Notes* and *Polycom RealPresence Collaboration Server 8.9.0 Administrator Guide*.

Installation and Upgrade Notes

For information on installation, please refer to the Polycom RealPresence Collaboration Server 8.9.0/8.9.0.2 Release Notes.