

Patch Notes

Polycom® RealPresence® Collaboration Server

Build ID: 8.5.13.314
Released File: OVA, ISO, BIN
Release Date: Oct 15, 2018
Part Number: NA

Purpose

This patch includes fixes for the following issues when applied over the RealPresence Collaboration Server 8.5.13.1 release.

ID	Description
EN-99935	Participants were disconnected at 00:29 on 26th July. McuInternalProblem Did not receive ACK for opcode: CONFPARTY_CM_CLOSE_UDP_PORT_REQ Req:1992305(Responsibility: embedded)
EN-103956	content sharing failure in cascading meeting.
EN-100461	RMX unexpected reboot in the conference. Core dump generated.
EN-101237	RMX1800 - MRMP-RtpRx0.RMX_8.5.21.86.1533892007.4253 coredump observed
EN-103563	RMX1800 slot 1 restart. RMX 1800 v8.5.21.86.
EN-103854	New core file was detectedSystemMonitoringNew core file was detected:ConfParty.RMX_8.5.13.297.1535789647

These patch notes document only the changes from the prerequisite generally available (GA) & 8.5.13.1 release. Please refer to the Release Notes for that GA release for the complete documentation of that release.

Prerequisites and Configuration Considerations

Please refer to the *Polycom RealPresence Collaboration Server v8.5 Administrator Guide*.

Installation Notes

Please refer to the *Polycom RealPresence Collaboration Server v8.5 Administrator Guide*.

Rollback Considerations

Please refer to the *Polycom RealPresence Collaboration Server v8.5 Administrator Guide*.