



Patch Release Notes

Polycom RealPresence Collaboration Server

Build ID: 8.10.0.4794
Released File: OVA, ISO, BIN, QCOW2, Upgrade File
Release Date: June 28, 2022
Part Number: 3725-87628-010

Purpose

This hotfix includes fixes for the following issues when applied over the RealPresence Collaboration Server 8.10.0.1 HF1 release.

<i>Issue ID</i>	<i>Category</i>	<i>Description</i>
EN-221147	General	RMX allows Secure Shell (SSH) key exchange algorithms that have security vulnerabilities.
EN-227279	General	RMX generates the major alarm “Unit not responding” when DSP units fail to recover due to memory errors on the media card.

These release notes document only the changes from the preceding generally available (GA) release. Refer to the Release Notes for that GA release for the complete release documentation.

Prerequisites and Configuration Considerations

For information on prerequisites and configuration, please refer to the *Polycom RealPresence Collaboration Server v8.10 Release Notes* and *Polycom RealPresence Collaboration Server 8.10 Administrator Guide*.

Installation and Upgrade Notes

For information on installation and upgrade, please refer to the Polycom RealPresence Collaboration Server 8.10 Release Notes.