



## Patch Notes

# Polycom<sup>®</sup> RealPresence<sup>®</sup> Collaboration Server

---

**Build ID:** 8.8.1.4184  
**Released File:** OVA, ISO, BIN, QCOW2, Upgrade File  
**Release Date:** August 31<sup>st</sup>, 2021

## Purpose

This patch includes fixes for the following issues when applied over the RealPresence Collaboration Server (RMX) 8.8.1.8 release.

<i>Issue ID</i>	<i>Category</i>	<i>Description</i>
EN-202635	Stability	Calls from a Cisco endpoint were rejected by the RMX system due to inconsistencies in encryption capabilities exchange.
EN-199918	Stability	After an RMX Virtual Edition (VE) system was restarted from VMware, it rebooted continuously until it was shutdown manually.

These patch notes document only the changes from the preceding Generally Available (GA) release. Refer to the Release Notes for that GA release for the complete release documentation.

## Prerequisites and Configuration Considerations

For information on prerequisites and configuration, please refer to the *Polycom RealPresence Collaboration Server v8.8.1 Release Notes* and *Polycom RealPresence Collaboration Server 8.8.1 Administrator Guide*.

## Installation and Upgrade Notes

For information on installation or upgrade, please refer to the Polycom RealPresence Collaboration Server 8.8.1/8.8.1.4 Release Notes.