

## Patch Notes

# Polycom<sup>®</sup> RealPresence<sup>®</sup> Collaboration Server

---

**Build ID:** 8.7.5.859  
**Released File:** OVA, ISO, BIN, Upgrade File  
**Release Date:** July 17, 2019

## Purpose

This patch includes fixes for the following issues when applied to the RealPresence Collaboration Server 8.7.5.6 release.

Issue ID	Category	Description
EN-142212	Audio	The first dial-out MS Lync client was unable to get audio in an ongoing conference when encryption was enabled.
EN-140351	Stability	The SIPtask hanged and recovery mechanism failed due to high signaling load so the user was unable to join the conference.
EN-141244	Stability	ConfParty core dump due to invalid data, which caused all active calls to drop.
EN-134337	Video	Frozen video observed in RealConnect calls when FEC and traffic shaping were enabled simultaneously.
EN-140354	Stability	The SIPtask terminated due to bulk notifications, which caused all active calls to drop.
EN-124907	Stability	Media card reboot observed on RMX 2000 causing all active calls to drop.

These patch notes document only the changes from the prerequisite generally available (GA) release. Refer to the Release Notes for that GA release for the complete release documentation.

## Prerequisites and Configuration Considerations

For information on prerequisites and configuration, please refer to the *Polycom RealPresence Collaboration Server v8.7.5 Release Notes* and *Polycom RealPresence Collaboration Server v8.7.1 Administrator Guide*.

## Installation and Upgrade Notes

For information on installation, please refer to the *Polycom RealPresence Collaboration Server v8.7.5 Release Notes*.