



Patch Release Notes

Polycom RealPresence Collaboration Server

Build ID: 8.9.2.4791
Released File: OVA, ISO, BIN, QCOW2, Upgrade File
Release Date: June 17, 2022
Part Number: 3725-87628-009

Purpose

This hotfix includes fixes for the following issues when applied over the RealPresence Collaboration Server 8.9.2.2 HF1 hotfix release.

Issue ID	Category	Description
EN-217662	Video	Intermittent video freeze was observed during a conference when all participants connected with a video resolution of 1080p and frame rate of 30 frames per second.
EN-225303	Video	Green video was displayed on the layout of conference participants when the RealPresence Mobile client app running on iOS was placed on the background.

These release notes only document the changes from the preceding generally available (GA) release. Refer to the Release Notes for that GA release for the complete release documentation.

Prerequisites and Configuration Considerations

For information on prerequisites and configuration, please refer to the *Polycom RealPresence Collaboration Server v8.9.2 Release Notes* and *Polycom RealPresence Collaboration Server 8.9.2 Administrator Guide*.

Installation and Upgrade Notes

For information on installation and upgrade, please refer to the *Polycom RealPresence Collaboration Server 8.9.2 Release Notes*.